



An illinova Company

Illinois Power Company  
Clinton Power Station  
P.O. Box 678  
Clinton, IL 61727  
Tel 217 935-5623  
Fax 217 935-4632

Walter G. MacFarland IV  
Senior Vice President  
and Chief Nuclear Officer

U-603109  
2C.220

November 17, 1998

Docket No. 50-461

10CFR50.73

Document Control Desk  
Nuclear Regulatory Commission  
Washington, D.C. 20555

Subject: Clinton Power Station - Unit 1  
Licensee Event Report No. 1998-036-00

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1998-035-00: Opening Incorrect Electrical Cubicle Causes Loss of Shutdown Cooling and Leads to Failure to Meet Technical Specification Required Action in the Required Time. This report is being submitted in accordance with the requirements of 10CFR50.73.

The enclosed report contains the following commitments:

- Training for potential transformers will be improved to include potential transformer purpose, location, potential pitfalls for error, and various potential transformer configurations.

Sincerely yours,

Walter G. MacFarland, IV  
Senior Vice President and  
Chief Nuclear Officer

MRS/krk

Enclosure

cc: NRC Clinton Licensing Project Manager  
NRC Resident Office, V-690  
Acting Regional Administrator, Region III, USNRC  
Illinois Department of Nuclear Safety  
INPO Records Center

9811270098 981117  
PDR ADOCK 05000461  
S PDR

11  
IE22