



Log # TXX-88808
File # 10110
903.9
Ref. # 10CFR50.55(e)

William G. Council
Executive Vice President

November 30, 1988

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
CABLE TRAY TEE FITTINGS
SDAR: CP-85-50 (SUPPLEMENTAL REPORT)

Gentlemen:

On September 30, 1987, we notified you via our final report logged TXX-6771 of a deficiency involving the use of improper welding processes in the manufacturing of cable tray tee fittings. Our latest supplemental report was logged TXX-88589, dated July 26, 1988. The purpose of this report is to update the status of the corrective actions for Unit 1.

Activities specified in TXX-88589 with an estimated completion date of November 30, 1988, have been rescheduled to March 1, 1989. If any modifications are required as a result of the engineering evaluation previously described in TXX-88589, we will notify you of the implementation schedule by March 1, 1989. The completion schedule for Unit 2 has not changed.

Very truly yours,

W. G. Council

RSB/mlh

c - Mr. R. D. Martin, Region IV w/o encl.
Resident Inspectors, CPSES (3) w/o encl.

6612060035 881130
DR ADDCK 05000445
PDC

IE27
1/0