

4 Repti - 2 of we have deepl.

963 971 972

November 1, 1996

Director of Nuclear Material Safety and Safeguards U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Director;

This letter is to inform you of the transfer activity of Electron Capture Detectors (ECD), from the possession of On-Site Instruments, to and from our customers, per CFR, Title 10, Chapter 1, §31.5, paragraph (c)(9)(i) and our quarterly report of sources. As stated in a letter of December 11th, 1989, we rent, lease and sell ECD's across the U.S. The HP ECD is a Ni<sup>63</sup> source of 15mci. The Varian ECD is a Ni<sup>63</sup> source of 8mci. The Outokumpu DOPS 2310 Probe contains Cm<sup>244</sup> and Am<sup>241</sup> sources at 60mCi and 30mCi, respectively. We operate with license number 34-24437-01. Source transfers and inventories for the third quarter 1996 are listed on the following pages.

Sincerely,

Du (Wh

David Cheetham Radiation Safety Officer

9906240365 961101 PDR RC # SSD PDR // Nies

# RECEIVED HOV 2 4 1997

# Source Inventory July 31,1996

Source S/N location

#### Hewlett-Packard Model 19233

L5968 OSI 7/96 L6520 OSI 7/96 L6816 OSI 7/96 M1366 OSI 7/96

L7012 OSI 7/96 L7044 OSI 7/96 L7046 OSI 7/96 M1362 OSI 7/96 L6937 OSI 7/96

### Hewlett-Packard Model G1223A

F3437 OSI 7/96 F3448 OSI 7/96

F4454 NEI-GTEL Milford, NH 5/15/96

F4455 OSI 7/96

F4456 OHM Philadelphia,PA 5/21/96 to OSI 7/26/96 F4479 OHM -Philadelphia,PA4/1/96 to OSI 7/26/96 F4483 OHM-Philadelphia,PA 2/26/96 to OSI 7/24/96 F4484 NEI-GTEL Milford,NH 5/15/96

F7983 OSI 7/96

F7996 NYtest Port Washington, NY 5/30/96

F8077 GEO CORP Golden, CO 7/19/94 to OSI 7/30/96

K0054 NYtest Port Washington, NY 5/30/96

### Outokumpu DOPS 144095

Am<sup>241</sup> 2767LX OSI 7/96 Cm<sup>244</sup> 1866LM OSI 7/96

Valco 140 BN

N189 OSI 7/96

Varian model 02-1972-00

A7461 OSI 7/96 A9202 OSI 7/96 A9203 OSI 7/96

# Source Inventory August 31,1996

Source S/N location

### Hewlett-Packard Model 19233

L5968 OSI 8/96 L6520 OSI 8/96 L6816 OSI 8/96 M1366 OSI 8/96

L7012 OSI 8/96 L7044 OSI 8/96 L7046 OSI 8/96 M1362 OSI 8/96 L6937 OSI 8/96

# Hewlett-Packard Model G1223A

F3437 OSI 8/96

F3448 OSI 8/96

F4454 NEI-GTEL Milford, NH 5/15/96

F4455 OSI 8/96

F4456 OSI to Brown & Root Wayne, PA 8/23/96

F4479 OSI to OHM Plaistow, NH 8/12/96

F4483 OSI 8/96

F4484 NEI-GTEL Milford, NH 5/15/96

F7983 OSI 8/96

F7996 NYtest Port Washington, NY 5/30/96

F8077 OSI 8/96

K0054 NYtest Port Washington, NY 5/30/96

### Outokumpu DOPS 144095

Am $^{241}$  2767LX OSI to RMT Columbus, OH 8/7/96 to OSI 8/12/96 to Meterox 8/26/96 to OSI 8/28/96 to Meredith-Boli & Assoc. 8/29/96 Cm $^{244}$  1866LM OSI to RMT Columbus, OH 8/7/96 to OSI 8/12/96 to Meredith-Boli & Assoc. 8/29/96

#### Valco 140 BN

N189

OSI 8/96

### Varian model 02-1972-00

A7461 A9202 OSI 8/96 OSI 8/96

A9203

OSI 8/96

# Source Inventory September 30,1996

Source S/N location

### Hewlett-Packard Model 19233

L5968 OSI 9/96 L6520 OSI 9/96 L6816 OSI 9/96 M1366 OSI 9/96

L7012 OSI 9/96 L7044 OSI 9/96 L7046 OSI 9/96 M1362 OSI 9/96 L6937 OSI 9/96

# Hewlett-Packard Model G1223A

F3437 OSI 9/96

F3448 OSI 9/96

F4454 NEI-GTEL Milford, NH 5/15/96 to OSI 9/18/96

F4455 OSI 9/96

F4456 OSI to Brown & Root Wayne, PA 8/23/96

F4479 OSI to OHM Plaistow, NH 8/12/96

F4483 OSI 9/96

F4484 NEI-GTEL Milford, NH 5/15/96 to OSI 9/18/96

F7983 OSI 9/96

F7996 NYtest Port Washington, NY 5/30/96 to OSI 9/4/96 to Roy F. Weston Burlington, MA 9/27/96

F8077 OSI 9/96

K0054 NYtest Port Washington, NY 5/30/96 to OSI 9/4/96

# Outokumpu DOPS 144095

Am<sup>241</sup> 2767LX Meredith-Boli & Assoc. 8/29/96 to OSI 9/9/96 Cm<sup>244</sup> 1866LM Meredith-Boli & Assoc. 8/29/96 to OSI 9/9/96

#### Valco 140 BN

N189

OSI 9/96

### Varian model 02-1972-00

A7461

OSI 9/96

A9202

OSI 9/96

A9203

OSI 9/96

OHM Remediation Services Corp.

7 Kelly Road

Plaistow, NH 03865

ECD S/N: F4479

GC S/N: 3203A42184

Attn:Heidi Pitard

Phone: 508-497-6140

NEI-GETL

Meadow brook Industrial Parkway

Milford, NH 03055

ECD S/N: F4454 & F4484

GC S/N: 3203A42182

Attn: Robert Kennedy

Phone: 603-672-4835

Brown & Root

993 Old Eagle School Road Suite 415

Wayne, PA 19087

ECD S/N: F4456

GC S/N:3203A41521

Attn: Chuck Meyer Phone: 610-971-0900

Nytest

60 Seaview Blvd.

Port Washington, NY 11050

ECD S/N's F7996 & K0054

Attn: Dr. Shaw

Phone: 516-625-5500

GC S/N: 3203A41846

Meredith-Boli & Assoc. 6701 Center Drive West Suite 900

Los Angeles, CA 90045

Outokumpu DOPS 144095 S/N:2767LX & 1866LM

Attn:Carl Lotzgesell Phone: 310-670-9221

# RECEIVED NOV 2 4 1997

963 dupe

November 1, 1997

Director of Nuclear Material Safety and Safeguards U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Director;

This letter is to inform you of the transfer activity of Electron Capture Detectors (ECD), from the possession of On-Site Instruments, to and from our customers, per CFR, Title 10, Chapter 1, §31.5, paragraph (c)(9)(i) and our quarterly report of sources. As stated in a letter of December 11th, 1989, we rent, lease and sell ECD's across the U.S.. The HP ECD is a Ni<sup>63</sup> source of 15mCi. The Varian ECD is a Ni<sup>63</sup> source of 8mCi. The Outokumpu DOPS 2310 Probe contains Cm<sup>244</sup> and Am<sup>241</sup>sources at 60mCi and 30mCi, respectively. We operate with license number 34-24437-01. Source transfers and inventories for the third quarter of 1996 are listed on the following pages.

Sincerely;

Mitch Baker Radiation Safety Officer

# Source Inventory July 31,1996

Source S/N location

Hewlett-Packard Model 19233

L5968 OSI 7/96
L6520 OSI 7/96
L6816 OSI 7/96
L7044 OSI 7/96
M1366 OSI 7/96
L7046 OSI 7/96

M1362 OSI 7/96 L6937 OSI 7/96

### Hewlett-Packard Model G1223A

F3437 OSI 7/96 F3448 OSI 7/96

F4454 NEI-GTEL Milford, NH 5/15/96

F4455 OSI 7/96

F4456 OHM Philadelphia,PA 5/21/96 to OSI 7/26/96 F4479 OHM -Philadelphia,PA4/1/96 to OSI 7/26/96 F4483 OHM-Philadelphia,PA 2/26/96 to OSI 7/24/96

F4484 NEI-GTEL Milford, NH 5/15/96

F7983 OSI 7/96

F7996 NYtest Port Washington, NY 5/30/96

F8077 GEO CORP Golden, CO 7/19/94 to OSI 7/30/96

K0054 NYtest Port Washington, NY 5/30/96

# Outokumpu DOPS 144095

Am<sup>241</sup> 2767LX OSI 7/96 Cm<sup>244</sup> 1866LM OSI 7/96

Valco 140 BN

N189 OSI 7/96

Varian model 02-1972-00

A7461 OSI 7/96 A9202 OSI 7/96 A9203 OSI 7/96

# Source Inventory August 31,1996

Source S/N location

### Hewlett-Packard Model 19233

L5968 OSI 8/96 L6520 OSI 8/96 L6816 OSI 8/96 M1366 OSI 8/96

L7012 OSI 8/96 L7044 OSI 8/96 L7046 OSI 8/96 M1362 OSI 8/96 L6937 OSI 8/96

#### Hewlett-Packard Model G1223A

F3437 OSI 8/96

F3448 OSI 8/96

F4454 NEI-GTEL Milford, NH 5/15/96

F4455 OSI 8/96

F4456 OSI to Brown & Root Wayne, PA 8/23/96

F4479 OSI to OHM Plaistow, NH 8/12/96

F4483 OSI 8/96

F4484 NEI-GTEL Milford, NH 5/15/96

F7983 OSI 8/96

F7996 NYtest Port Washington, NY 5/30/96

F8077 OSI 8/96

K0054 NYtest Port Washington, NY 5/30/96

### Outokumpu DOPS 144095

Am<sup>241</sup> 2767LX OSI to RMT Columbus, OH 8/7/96 to OSI 8/12/96 to Meterox 8/26/96 to OSI 8/28/96 to Meredith-Boli & Assoc. 8/29/96 Cm<sup>244</sup> 1866LM OSI to RMT Columbus, OH 8/7/96 to OSI 8/12/96 to Merterox 8/26/96 to OSI 8/28/96 to Meredith-Boli & Assoc. 8/29/96

# Valco 140 BN

N189

OSI 8/96

#### Varian model 02-1972-00

A7461 A9202

OSI 8/96

M72U2

OSI 8/96

A9203

OSI 8/96

# Source Inventory September 30,1996

Source S/N location

### Hewlett-Packard Model 19233

L5968 OSI 9/96 L6520 OSI 9/96 L6816 OSI 9/96 M1366 OSI 9/96

L7012 OSI 9/96 L7044 OSI 9/96 L7046 OSI 9/96 M1362 OSI 9/96 L6937 OSI 9/96

# Hewlett-Packard Model G1223A

F3437 OSI 9/96

F3448 OSI 9/96

F4454 NEI-GTEL Milford, NH 5/15/96 to OSI 9/18/96

F4455 OSI 9/96

F4456 OSI to Brown & Root Wayne, PA 8/23/96

F4479 OSI to OHM Plaistow, NH 8/12/96

F4483 OSI 9/96

F4484 NEI-GTEL Milford, NH 5/15/96 to OSI 9/18/96

F7983 OSI 9/96

F7996 NYtest Port Washington, NY 5/30/96 to OSI 9/4/96 to Roy F. Weston Burlington, MA 9/27/96

F8077 OSI 9/96

K0054 NYtest Port Washington, NY 5/30/96 to OSI 9/4/96

# Outokumpu DOPS 144095

Am<sup>241</sup> 2767LX Meredith-Boli & Assoc. 8/29/96 to OSI 9/9/96 Cm<sup>244</sup> 1866LM Meredith-Boli & Assoc. 8/29/96 to OSI 9/9/96

#### Valco 140 BN

N189

OSI 9/96

### Varian model 02-1972-00

A7461

OSI 9/96

A9202

OSI 9/96

A9203

OSI 9/96

OHM Remediation Services Corp.

7 Kelly Road

Plaistow, NH 03865

ECD S/N: F4479

GC S/N: 3203A42184

Attn:Heidi Pitard

Phone: 508-497-6140

NEI-GETL

Meadow brook Industrial Parkway

Milford, NH 03055

ECD S/N: F4454 & F4484

GC S/N: 3203A42182

Attn: Robert Kennedy Phone: 603-672-4835

Brown & Root

993 Old Eagle School Road Suite 415

Wayne, PA 19087

ECD S/N: F4456

GC S/N:3203A41521

Attn: Chuck Meyer

Phone:610-971-0900

Nytest

60 Seaview Blvd.

Port Washington, NY 11050

ECD S/N's F7996 & K0054 GC S/N: 3203A41846

Attn: Dr. Shaw

Phone: 516-625-5500

Meredith-Boli & Assoc.

6701 Center Drive West Suite 900

Los Angeles, CA 90045

Outokumpu DOPS 144095 S/N:2767LX & 1866LM

Attn:Carl Lotzgesell Phone:310-670-9221