

Universal Testing Company
License No. 43-11213-01

Notice of Violation

Based on the results of the NRC inspection conducted on July 19, 1978, certain activities appear to be in noncompliance with NRC regulations and the conditions of your NRC License No 43-11213-01 as indicated below:

1. Contrary to License Condition 16, which requires that byproduct material be used in accordance with application dated October 31, 1972, amended February 9, 1973, and August 27, 1973, a copy of the Radiographer Qualification Examination in Radiation Safety for one radiographer was not maintained on file.

This is an infraction.

2. Contrary to 10 CFR 34.26, the quarterly physical inventory conducted February 17, 1978, did not account for all sealed sources in that it did not include an iridium-192, Gamma Industries Model A-1-A, Serial Number R23.77, sealed source purportedly possessed at that time.

This is a deficiency.

3. Contrary to 10 CFR 30.51, a record of receipt for an iridium-192, Gamma Industries Model A-1-A, Serial Number R23.77, sealed source was not maintained on July 19, 1978.

This is a deficiency.