

APPENDIX B

U. S. NUCLEAR REGULATORY COMMISSION  
REGION IV

NRC Inspection Report: 50-267/85-28

License: DPR-34

Docket: 50-267

Licensee: Public Service Company of Colorado (PSC)  
P. O. Box 840  
Denver, Colorado 80201

Facility Name: Fort St. Vrain Nuclear Generating Station (FSV)

Inspection At: Platteville, Colorado

Inspection Conducted: September 30 through October 4, 1985

Inspectors:

R. A. Caldwell  
R. A. Caldwell, Physical Security Specialist  
Emergency Preparedness and Safeguards Programs  
Section

3-21-86  
Date

A. B. Earnest  
A. B. Earnest, Physical Security Specialist  
Emergency Preparedness and Safeguards Programs  
Section

3/21/86  
Date

J. A. F. Kelly  
J. A. F. Kelly, Senior Physical Security  
Specialist, Emergency Preparedness and  
Safeguards Programs Section

21 Mar 86  
Date

Approved:

L. A. Yandell  
L. A. Yandell, Chief, Emergency Preparedness and  
Safeguards Programs Section

3/24/86  
Date

Inspection Summary

Inspection Conducted September 30 through October 4, 1985 (Report 50-267/85-28)

Areas Inspected: Routine, unannounced inspection of physical barriers - protected area, assessment aids/lighting, security program audit, security organization, testing and maintenance, locks, keys and combinations, training and qualification, compensatory measures, and management controls - security program.

Results: Within the areas inspected, nine violations were identified; physical barriers - protected area (response), paragraph 2; physical barriers - protected area (fences), paragraph 3; physical barriers - protected area (isolation zone), paragraph 4; physical barriers - protected area (bullet resistant glazing), paragraph 5; assessment aids, paragraph 6; security program audit, paragraph 7; security organization, paragraph 8; testing and maintenance, paragraph 9; and lock and key control procedures, paragraph 10). One deviation was identified (failure to meet commitment for repairing IDS, paragraph 12).

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION.  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED.