

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

8 9 M A P S 1 2 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 50

8 REPORT SOURCE L 6 0 5 0 - 0 2 9 3 7 1 1 2 1 7 8 8 1 1 2 2 7 8 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 On 11/21/78, PNPS management was informed of OA audit 78-18, which identified an oc-

3 currence that was contrary to limiting conditions for operations as specified in T.S.

4 section 3.2.C.1 and Table 3.2.c. On 10/30/78 the number of operable SRMs was reduced

5 below the minimum required when SRM "A" was jumpered to eliminate problems with the

6 downscale rod block. A reactor startup was in progress and SRM "D" was already by-

7 passed because of a failed detector.

8 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

9 I A (11) A (12) C (13) I N S T R U (14) E (15) Z (16)

17 LER/RO REPORT NUMBER 7 8 0 5 1 0 1 X 0

EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 28 29 REPORT TYPE 30 31 REVISION NO. 32

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 40 ATTACHMENT SUBMITTED 41 NPRD-4 FORM SUB. 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 44 47

G 18 H 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 G 0 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 This event occurred when maintenance and repair personnel inadvertently jumpered out the

1 entire "A" SRM trip logic instead of only the downscale trip as approved by ORC.

2 Station procedure 3.M.1-3 is being revised to require ORC approval of the specific

3 location of jumper terminals to ensure that only those functions which are not required

4 are affected.

8 9 FACILITY STATUS 28 % POWER 29 OTHER STATUS 30 METHOD OF DISCOVERY 31 DISCOVERY DESCRIPTION 32

5 C 28 0 0 0 29 N.A. 30 C 31 QA Audit

8 9 ACTIVITY CONTENT 33 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

6 Z 33 Z 34 N.A. N.A.

PERSONNEL EXPOSURES 37 38 DESCRIPTION 39

7 0 0 0 37 Z 38 N.A.

PERSONNEL INJURIES 40 41 DESCRIPTION 41

8 0 0 0 40 N.A.

LOSS OF OR DAMAGE TO FACILITY 43

9 Z 43 N.A.

8 9 PUBLICITY ISSUED 45 DESCRIPTION 45

0 N 45 N.A.

NRC USE ONLY

7811280335- Charles J. Mathis

NAME OF PREPARER

68 69 617-746-7900

PHONE:

80 81 82 83 84