F13 - 8 1382

Docket No. 30-07022

Radiation Technology, Inc. ATTN: Martin A. Welt, Ph.D. President 108 Lake Denmark Road Rockaway, New Jersey 07866

Gentlemen:

Subject: Inspection No. 30-07022/81-01

This refers to your letter dated August 6, 1981, in response to our letter dated July 28, 1981.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

With regard to your response to Item A in the Notice of Violation, you are advised that your operation of the product conveyor system without having the exit portal equipped as required constituted noncompliance with 10 CFR 20.203(c)(6)(viii) regardless of the fact that you requested an exemption to this requirement. While we recognize the delay in our response to your request for an exemption, a licensee is required to adhere to all regulatory requirements until such time as relief from a requirement has been specifically granted by the NRC. We understand from your letter that you are now prepared to install a system which fulfills the requirements of 10 CFR 20.203(c)(6)(viii). You are advised that the operation of your product conveyor system without the required equipment on the exit portal would constitute recurrent noncompliance.

Your cooperation with us is appreciated.

Thomas T. Martin, Director Division of Engineering and

Technical Inspection

ostello/qwc

8202190231

cc: Public Document Room (PDR) Nuclear Safety Information Center (NSIC) State of New Jersey

bcc: Region I Docket Room (with concurrences)