



INTERPOLL INC.
4500 BALL ROAD N.E.
CIRCLE PINES, MINNESOTA 55014
612/786-6020

October 5, 1987

U.S. NUCLEAR REGULATORY COMMISSION
Region III
Materials Licensing Section
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear sirs:


This letter will serve as our official request for termination of our special license for Model #19303 Electron Capture Detector.

We have exchanged the Model #19303 for a Model 19312 ECD which only requires a general license.

We have enclosed a copy of the Hewlett Packard invoice and other documents in support of our request for license termination.

If you have any questions regarding our request, please feel free to contact me.

Sincerely,



Richard R. Dahl,
Director of Analytical Services

RRD/cg

Enclosures

RECEIVED
OCT 08 1987
REGION III

8806150298 871020
REG3 LIC30
22-19911-01 PDR


OCT 8 1987

ATTN: CINDY

INVOICE NO 3GX3667

PAGE: 1 OF 1

PLEASE SEND ALL REMITTANCES TO:



P.O. BOX 92013

CHICAGO

ILL 60675

ORDER
DATE

07/20/87

INVOICE
DATE

07/21/87

DUE
DATE

08/20/87

PAYMENT
TERMS

NET/30

HP
ORDER NO

264351676001

CUSTOMER PURCHASE
ORDER NO

7564JB51

DUNS05-057-2536 Federal EIN 94-1081436

INVOICE TO:

INTERPOLL INC
4500 BALL ROAD N.E.
CIRCLE PINES

MN 55014

SPECIAL INSTRUCTIONS:
FOR BILLING ONLY

PLEASE DIRECT ALL INQUIRIES TO:

HEWLETT-PACKARD COMPANY
ROUTE 41

AVONDALE

PA 19311

PHONE (800) 227-9770

SUMMARY:

ITEMS TOTAL:

\$459.00

TAX(SEE DESCRIPTION BELOW):

\$27.00

INVOICE TOTAL:

\$486.00

ITEM	PRODUCT	DESCRIPTION	QTY	UM	UNIT PRICE	AMOUNT
------	---------	-------------	-----	----	------------	--------

SHIP TO:

INTERPOLL INC
4500 BALL ROAD N.E.
CIRCLE PINES
M/F JEFF BUSHNER

MN 55014

0100	19312-69550	CUSTOMER ORDER ONLY-USA	1	EA	450.00	450.00
22		SPECIAL HANDLING	1	EA	9.00	9.00
	PRICE FOR 0100					459.00
	SALES/USE TAX FOR 0100				27.00	

SHIPPED VIA:

SHIP DATE:07/21/87 B/L NUMBER:

TAX TOTAL: MINNESOTA STATE TAX
INVOICE TOTAL:27.00
486.00RECEIVED
JUL 27 1987
INTERPOLL INC.

PLEASE SEND INVOICE COPY OR REFERENCE INVOICE NO. 3GX3667 AND REMIT

486.00

ORIGINAL

7/15/87

HEWLETT  PACKARD

SHIP TO

INTERPOL INC
4500 BALL RD NE
CIRCLE PINES MN 55014


4307F-049A

OT	ORDER NUMBER	SECTION
	264351676	001

M/F JEFF BUSHNER 612 786-6020

FOR SHIPPING ONLY/ EC EXCHANGE PROGRAM
BILLING TO FOLLOW

SOLD TO

CUSTOMER ORDER NUMBER 7564JB51				GOVERNMENT CONTRACT NUMBER				H.P. GSA H.P. PURCH				H.P. QUOTE NO.			
TY	CUSTOMER NO.	CT	W-CR	ENG	T.R.C.	RATING	REQ DATE	DISC MFG	DISC REG	DISC S.O.	TERMS				
CPR	INSP	FAST	COC	INS	2 MAN	NO	DD	SHIP VIA INSTRUCTIONS				CAO			
				P		PARTIAL 250		FEDERAL EXPRESS							
SPECIAL INSTRUCTIONS															
				 				393 883 192							
CUSTOMER PACKAGE TRACKING NUMBER -- PULL UP PURPLE TAB															
SHIP DATE		METHOD		CARRIER		FREIGHT		COD CHG		PARTIAL NO					
7/16/87		air		Freci		\$400				10		II			
ITEM	SUB	INT	PRODUCT NUMBER		DESCRIPTION				SUB-UNIT PRICE	MKTSUF-QC	ID	QTY ORDER	REQ DATE SPECIAL	QTY AUX	QTY SH
			19312-69550									1			
5/0552															
07-16-87															

HEWLETT PACKARD CO.

ROUTE 41
AVONDALE, PA 19311
THIS PACKAGE CONFORMS TO THE
CONDITIONS AND LIMITATIONS
SPECIFIED IN 49 CFR 173.422
FOR EXCEPTED RADIOACTIVE MATERIAL,
INSTRUMENTS AND ARTICLES, WHATEVER

PINK COPY TO ED HOFFMAN

HEART SYSTEM
SHIPPING ORDER

BYPRODUCT MATERIALS (RADIOACTIVE) LICENSE VERIFICATION

For new purchase and return for exchange of specific license radioactive electron capture detectors no. 18713A, 18803-60520, and 19303. Also for return for exchange of general license detectors no. 19282 and 19312, and for purchase of conversion kits 19283 and 19393. For use within the U.S. only.

For new purchase of general license detector no. 19282 or 19312, customer certification card part no. 43-5953-1586 must be completed.

INSTRUCTIONS:

1. Complete section A below. Read section B and complete the appropriate certification statement (specific license below, general license on reverse side).
2. For new purchases mail this form to your local HP sales office.
3. For returns for exchange/servicing of used detectors, see section C reverse side.

A. COMPANY InterPoll, Inc. CUSTOMER NAME Jeffrey Bushner
ADDRESS 4500 Ball Rd. NE CUSTOMER P.O. NO. 75643251
Circle Pines, MN 55014 HP SALES OFFICE _____
HP SALES ORDER NO. _____
TELEPHONE NO. (612) 786-6020 TAX STATUS TAXABLE ☐ EXEMPT ☐

B. LICENSE VERIFICATION

Failure to comply with licensing requirements can cause serious consequences for both your company and Hewlett-Packard. Having a designated licensee read and complete the applicable certification statement (specific license below, general license on reverse side) will serve as a check that you are properly licensed to receive the material indicated.

SPECIFIC LICENSE CERTIFICATION

The Nuclear Regulatory Commission Regulations require Hewlett-Packard to have on file verification of your N.R.C. License (or State License if you live in an "Agreement" State) before shipping your detector. This license must be current and it must apply to the type, quantity, and form being purchased on the above-referenced order. (See latest revision of HP form 5950-5145, CFR Title 10, and NRC form 313 and Regulatory Guide 10.7 for licensing information).

This is to certify that our N.R.C. or Agreement State License is current and permits us to receive the type, quantity, and form of radioactive materials for the use specified as described below.

QTY	NEW PURCHASE	EXCHANGE	CLEAN	REBUILD	SERIAL NO.
_____ HP EC Detector no. 18713A, 15 mCi Ni63 plated part, for use on 5700 series gas chromatographs.	☐	☐			_____
_____ HP EC Detector no. 18803-60520, 15 mCi Ni63 plated part, for use on 5830/5840 series gas chromatographs.	☐	☐			_____
<u>1</u> HP EC Detector no. 19303, 15 mCi Ni63 plated part, for use on 5880 series gas chromatographs.	☐	☒			<u>S-9288</u>
_____ HP Accessory no. 19283, for converting general license EC (19282) to specific license (18713A).	☐				_____
_____ HP Accessory no. 19393, for converting general license EC (19312) to specific license (19303).	☐				_____
_____ HP EC Detector no. 2-6195, 2 mCi Ni63 foil (NRD, N-1002), for use on 402, 700, 5750, and 7610/20 series gas chromatographs.			☐	☐	_____

LICENSE NUMBER 22-19911-01
ISSUING AGENCY NRC
EXPIRATION DATE Feb 28 1991

Rick R. D. D.
SIGNATURE OF AUTHORIZED OFFICER OR LICENSED USER
DATE July 9th 1987

GENERAL LICENSE CERTIFICATION

(For exchange of general license detectors only. New purchase of general license EC detectors requires completion of customer certification card, part no. 43-5953-1586).

This is to certify that we understand and are in compliance with regulations governing the general license EC detector described in Information for General Licensees (part no. 43-5953-1586).

QTY		EXCHANGE	SERIAL NO.
	HP EC Detector No. 19312, 15mCi Ni63 plated part, general license EC for use on 5880 series gas chromatographs.	☐	
	HP EC Detector no. 19282, 15 mCi Ni63 plated part, general license EC for use on 5700 series gas chromatographs.	☐	

SIGNATURE OF GENERAL LICENSEE

DATE

C. EC DETECTOR EXCHANGE PROGRAM - EC Detectors no. 18713A, 18803-60520, 19282, 19303, 19312

HP will ship a rebuilt detector subject to the following:

- This form must be properly completed and accompanied by a fully assembled detector no. 18713A, 18803-60520, 19282, or 19303-60550 (See your manual).
- This program does not apply to any electronic parts or non-standard hardware. Any such items received will be returned with the rebuilt detector.
- All rebuilt detectors are guaranteed to meet HP specifications for new detectors.
- HP must receive the used detector before a replacement detector can be shipped. A rebuilt detector will be shipped within five working days after receipt of the used detector.
- Unless otherwise specified, return shipments will be by the fastest available method. All shipments will be FOB origin, freight prepaid and added to the invoice.
- For prices, call your local HP sales office and request the price for the appropriate exchange part number shown below.

When returning a detector for exchange,

1. Do not place an order with your local office. Leave blank the space for sales order number on the reverse side.
2. Consult your radiation safety officer and the latest revision of the Code of Federal Regulations, Titles 10 and 49 (sec. 173.391), and applicable local and state regulations for packaging, labeling and shipping instructions.
3. Send this form, a copy of your purchase order, and the detector directly to:

EC Detector Exchange Program
Hewlett-Packard Co. - Avondale Division
Rte 41 & Starr Rd.
Avondale, Pennsylvania 19311

NOTE: If your detector is covered by warranty or by an HP service contract, contact your local service engineer before shipping your detector. The engineer will provide an order number to be entered on the reverse side instead of your purchase order number. In this case, you need not supply a purchase order.

Model No.	Detector No.	Exchange Part No.
5700 Series	18713A, 19282	18713-69501
5830/40 Series	18803-60520	18803-69520
5880 Series	19303, 19312	19303-69550

Older Instruments

EC Detector no. 2-6195 is not included in the exchange program, but can be returned to Avondale Division for servicing. Please send this completed form and the detector directly to the attention of "EC Detector Service" at the above address. Allow 6-8 weeks for delivery.

