Arizona Public Service Company June 5, 1984 ANPP-29664-TDS/TRE U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368 Attention: Mr. T. W. Bishop, Director Division of Resident Reactor Projects and Engineering Programs Time Extension For Report - DER 84-18 Subject: A 50.55(e) Potentially Reportable Deficiency Relating To Wiring Error On LPSI 'B' Pump CS-3 Switch. File: 84-019-026; D.4.33.2 Reference: (A) Telephone conversation between P. Narbut and T. Bradish on March 26, 1984 (B) ANPP-29315, dated April 18, 1984 (Interim Report) Dear Sir: The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by June 12, 1984. Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by July 18, 1984, at which time a complete report will be submitted. There is no new information or change to the Interim Report at this time. Very truly yours, E. E. Van Brunt, Jr. 18K APS Vice President Nuclear Production ANPP Project Director EEVB/TRB:db cc: See Page Two 8406180218 840 PDR ADOCK 0500 IE- 27.10 Mr. T. W. Bishop DER 84-18 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

L. A. Souza

B. S. Kaplan

D. E. Fowler

T. D. Shriver

C. N. Russo

J. Vorees

J. R. Bynum

J. M. Allen

J. A. Brand

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

G. A. Fiorelli

S. R. Frost

J. Self

D. Canady

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339