

Illinois Power Company Clinton Power Station P.O. Box 678 Clinton, IL 61727 Tel 217 935-5623 Fax 217 935-4632

Walter G. MacFarland IV Senior Vice President and Chief Nuclear Officer

> U-603133 2C.220

December 18, 1998

Docket No. 50-461

10CFR50.73

Document Control Desk Nuclear Regulatory Commission Washington, D.C. 20555

Subject:

Clinton Power Station - Unit 1

Licensee Event Report No. 1998-026-00

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1998-026-00: Incorrect Supplier Design Results in Inoperable Electric Power Assembly (EPA) Circuit Cards Which Monitor Power to the Reactor Protection System (RPS) SCRAM and Main Steam Isolation Valve Solenoid Valves. This report is being submitted in accordance with the requirements of 10CFR50.73.

The enclosed report contains a commitment for CPS to procure EPA circuit cards correctly designed in accordance with the design specification and to install them in the two RPS UPS inverters.

Sincerely yours,

George a. Hunger, fr.
For Walter G. MacFarland, IV
Senior Vice President and

Chief Nuclear Officer

RSF/krk

Enclosure

cc: NRC Clinton Licensing Project Manager

177

NRC Resident Office, V-690

Acting Regional Administrator, Region III, USNRC

Illinois Department of Nuclear Safety

**INPO Records Center** 

9812300334 981218 PDR ADOCK 05000461 S PDR 5.622