

0695

UNITED STATES GYPSUM COMPANY //

1255 Raritan Road / Clark, New Jersey 07066

August 6, 1986

Director of Nuclear Material
Safety & Safeguards
U.S. Nuclear Regulatory Commission
Washington, DC 20555


Dear Sir/Madam:

Please be advised that the Clark Plant of the United States Gypsum Company has removed from service the equipment that used 500 μ Ci of Kr-85 isotope. *m*

The source was returned to the Accuray Corporation of Columbus, Ohio per attached letter dated 7/31/86.

Very truly yours,

United States Gypsum Company



Robert H. Taylor
Technical Superintendent


RHT/ckp

Attachment

'86 AUG 13 A9:53

NK2311

9901120430 B60806
PDR RC * PDR
SSD



July 31, 1986

U.S. Gypsum Company
Att: Robert Taylor
Technical Superintendent
1255 Raritan Road
Clark, NJ 07066

Dear Sir:

Please be advised that the following source was received at AccuRay Corporation, Columbus, Ohio and is now in our possession under USNRC Byproduct Material License 34-00255-03.

<u>Date</u>	<u>Source</u>			<u>Source</u>	<u>Device</u>
<u>Received</u>	<u>Serial No.</u>	<u>Isotope</u>	<u>Quantity</u>	<u>Model</u>	<u>Model</u>
7-28-86	K-3448-X	Kr-85	500 mCi	S-11	O-3

To comply with the requirement for notification of transfer in the Code of Federal Regulations Title 10, Part 31.5, we recommend you forward a copy of this letter to:

Director of Nuclear Material Safety & Safeguards
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Very truly yours,

Doris Kramer
Administrator
Radiological Operations