NRC Form 591 (13/81)	and an		U.S. NUCLEAR REGULAT	ORY COMMISSION
10°CFR 2.201	SAFETY I	NSPECTION		
P.O. BOX 6 SHAWNEE, OKLAHOMA 74801		2 REGIONAL OFFICE U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Dr., Ste. 1000 Arlington, Texas 76011		
030-05955	4. LICENSE NUMBERIST	090-01	MAY 27,198	36
The inspection was an examination of the activitie Regulatory Commissions (NRC) rules and regulation and representative records, interviews, with person 1. Within the scope of this inspection, no viola 2. The inspector also verified the steps you have those actions at this time 3. During this inspection certain of your activity	ons and the conditions of you mel, and observations by the stions were observed. ve taken to correct the violati	in license. The inspection inspector. The findings a ions identified during the	n consisted of selective examina is a result of this inspection are last inspection. We have no fu	tions of procedures as follows:
THIS IS A NOTICE OF VIOLATION whice A of a B. Containers located in labeled to indicate the presence of radio	h is required to be posted in :	accordance with 10 CFR	19.11	ndicate the presence (c), (d), (e) or 34.42 were not properly
D. Records of 20, 401	RG TO RADIATION A	License Co	were not i	property maintained
E. Documents were not properly posted or F. Reports or notifications of with 10 CFR	-	0 CFR 19.11. or License Condition Nur	were not	made in accordance
MAINTAINED AS REQUI	UMENT CALIBRA	TION WERE	NOT PROPERLY	SECTION
В606240620 8606 REG4 LIC30 35-13090-01	910			x E. of
I hereby state that within 30 days the actions desc This statement of corrective actions is made in acc the NRC SIGNATURE - LICENSEE		Prinzo		