

Point Beach Nuclear Plant 6610 Nuclear Rd., Two Rivers, WI 54241 (920) 755-2321

NPL 98-0056

9

January 27, 1998

Document Control Desk U.S. NUCLEAR REGULATORY COMMISSION Mail Station P1-137 Washington, DC 20555

Ladies/Gentlemen:

DOCKETS 50-266 AND 50-301 COMMITMENT UPDATE NRC INSPECTION REPORTS 50-266/97016 AND 50-301/97016 POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

By letter dated October 17, 1997, forwarded the results of an inspection conducted by your staff at our Point Beach Nuclear Plant fron. July 27 through September 8, 1997. The inspection report contained a Notice of Violation. Wisconsin Electric responded to the Notice by letter dated November 14, 1997.

Violation 2 of the Notice documented two instances of Residual Heat Removal loop inoperability for reasons other than surveillance testing with reactor coolant temperature less than 140°F; a condition prohibited by Technical Specification 15.3.1.A.3.b. In response to this violation, Wisconsin Electric committed to submit a license amendment request incorporating appropriate provisions consistent with NUREG-1431 to resolve this prohibition. Our November 14, 1997, response also indicated that we expected to submit our request in January 1998.

The purpose of this letter is to inform you that our submittal will be delayed beyond January 1998. It is our desire to submit a comprehensive and complete submittal that appropriately incorporates requirements for decay heat removal into the Point Beach Technical Specifications consistent with the industry standards delineated in NUREG-1431 for Westinghouse reactors and the Point Beach Nuclear Plant design bases. Due to the significance of this change, additional time is necessary to complete the submittal and the required administrative and technical revie.vs. We expect a draft of the proposed changes will be ready for internal reviews in early February. This amendment application remains a priority for submittal to the Commission.

9802050086 980 ADOCK



TEOID

NPL 98-0056 Page 2

We regret any inconvenience this change may have caused. Please contact us if you have any questions.

lean to tar

Scott A. Patulski Site Vice-President

cc: NRC Resident Inspector NRC Regional Administrator