

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 R'AN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

January 15, 1999

Mr. William C. Head Radiation Safety Officer Raytheon Support Services Company 315 Inverness Way South Englewood, Colorado 80112

SUBJECT: INRC INSPECTION REPORT 030-32673/98-01 (FORM 591)

Dear Mr. Head:

This letter and the enclosed NRC Form 591 refer to the safety inspection completed on December 1, 1998, at your facility at Wright-Patterson Air Force Base, Ohio. The inspection included a review of activities authorized by Byproduct Materials License 05-27429-01. Additionally, a telephonic exit briefing was subsequently conducted with you on January 4, 1999.

Within the scope of this inspection no violations or deviations were identified; therefore, no response to this letter or the enclosed NRC Form 591 is required.

Should you have any questions concerning this letter, please contact the undersigned at (817) 860-8164 or Elmo E. Collins at (817) 860-8291.

Sincerely,


Emo 2.

Jeffrey Cruz, Radiation Specialist Nuclear Materials Inspection Branch Division of Nuclear Materials Safety

Docket No.: 030-32673 License No.: 05-27429-01

Enclosure: As stated

cc w/enclosure: Colorado Radiation Control Program Director Ohio Radiation Control Program Director



Raytheon Support Services Company -2-

E-Mail report to Document Control Desk (DOCDESK)

bcc to DCD (IE07)

.

bcc distrib. by RIV: RIV Regional Administrator LLHowell EECollins CLCain MRShaffer \*JCruz \*NMIB MIS System \*RIV Nuclear Materials File - 5th Floor

\*W/IFS Form

## 250006

DOCUMENT NAME: Draft: G:\NMIS.O\JC\RAYTHEON.WPD Final: r:\\_dnms\83267301.jxc To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:DMMS/NMIB	C:NMIB		
JCruž:WsW/	EEÇøhine		
11/199	1/\5/99		

OFFICIAL RECORD COPY