Commonwealth Edison Company LaSafic Generating Station 2601 North 21st Road Marseilles, II. 61341-9757 *Tel 815757-6761

ComEd

January 30, 1998

United States Nuclear Regulatory Commission Attention: Document Control Desk Washington, D.C. 20555

Licensee Event Report #97-039-01, Docket #050-373 is being submitted to your office to update the safety analysis.

The report contains the following new commitments:

The immediate corrective action was to analyze the tailpipe restraints including seismic loads for Unit 1. The evaluation and analyses of tailpipes found to be unanalyzed for seismic loads are continuing for Unit 2. (NTS # 373-180-97-SCAQ00039S1.01)

A supplemental LER will be submitted to report the results for Unit 2. (NTS # 373-180-97-SCAQ00039S200)

If there are any questions or comments concerning this letter, please refer them to Perry Barnes, Regulatory Assurance Manager, at (815) 357-6761, extension 2383.

Respectfully,

Fred Dacimo

Site Vice President

LaSalle County Station

Enclosure

cc: A. B. Beach, NRC Region III Administrator

M. P. Huber, NRC Senior Resident Inspector - LaSalle

C. H. Mathews, IDNS Resident Inspector - LaSalle

F. Niziolek, IDNS Senior Reactor Analyst

INPO - Records Center

9802060227 980130 PDR ADDCK 05000373 S



A Unicom Company

022