

SM-97-110

November 20, 1997

United States Nuclear Regulatory Commission
Washington, DC 20555

Attention: Document Control Desk

Reference: Quad Cities Nuclear Power Station
Docket Number 50-254, DPR-29, Unit One

1. Licensee Event Report (LER) 254/97-021, Revision 00, dated September 25, 1997 (SVP-97-198), Titled, "The Cause of Discrepancies Found Between the Safe Shutdown (SSD) Procedures and the Fire Protection Report, Which Led to the Declaration That Nine SSD Paths Were Inoperable, Is Unknown at This Time."

This letter is being submitted to inform you that the following commitments will not be completed by the dates listed in reference (1). The original commitments and due dates are as follows:

1. Complete a Root Cause Analysis Investigation as discussed in Section C of this LER by 112197.
2. Submit a supplemental LER by 120597.

A completion date extension is necessary due to an expanded scope that developed for the subject root cause analysis investigation. Factors contributing to this scope change include: (1) additional research into events that occurred over 8 years ago was required and (2) locating and interviewing personnel from the late 1980's was time consuming. Revised completion dates for the above action items are as follows:

1. The subject Root Cause Analysis will be completed by 120597.
2. A supplemental LER will be submitted by 121997.

9712020071 971120
PDR ADX JK 05000254
PDR

STMGR\LER\97110.DBC




November 20, 1997

If there are any questions or comments concerning this letter, please refer them to Charles Peterson, Regulatory Affairs Manager at 309-654-2241, ext. 3609.

Respectfully,

COMMONWEALTH EDISON COMPANY
QUAD CITIES STATION



D. B. Cook
Station Manager

DBC/CP/plm

cc: A. B. Beach, Regional Administrator, Region III
R. M. Pulsifer, Project Manager, NRR
C. G. Miller, Senior Resident Inspector, Quad Cities
M. E. Wagner, Licensing, ComEd
S. D. Killian, Engineering, ComEd, Quad Cities