JUN 2 7 1986

Docket No. 030-28820

License No. 37-20891-01

Springfield Medical Imaging Center ATTN: Donald Kasper, M.D. P.O. Box 247 Baltimore Pike and Andrew Road Springfield, Pennsylvania 19064

Gentlemen:

Subject: Inspection No. 86-01

This refers to the routine safety inspection conducted by Marlene J. Taylor of this office on April 22, 1986 of activities authorized by NRC License No. 37-20891-01 and to the discussions of our findings held by Mrs. Taylor with Mr. G. Trovato of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Based on the results of this inspection, it appears that certain of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. These violations have been categorized by severity level in accordance with the revised NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register Notice (49 FR 8583) dated March 8, 1984. You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

Item A described in the attached Notice of Violation, involving control of licensed material, is classified as a Severity Level IV violation. As indicated in Supplement IV of the NRC Enforcement Policy, significant violations of this type are normally classified as Severity Level III. However, after careful consideration of the factors involved in this specific instance, we have exercised our judgement under the NRC Enforcement Policy and have classified this violation as Severity Level IV. Similar violations of this type in the future may result in additional enforcement action.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

8607100394 860627 REG1 LIC30 37-20891-01 PDR

OFFICIAL RECORD COPY DL SPRI

DL SPRINGFIELD MED - 0001.0.0 04/30/86

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By: John D. Kinneman

John D. Kinneman, Chief Nuclear Materials Safety Section A. Division of Radiation Safety and Safeguards

Enclosure: Appendix A, Notice of Violation

cc w/encl: Public Document Room (PDR) Nuclear Safety Information Center (NSIC) Commonwealth of Pennsylvania

bcc w/encl: Region I Docket Room (w/concurrences) Management Assistant, DRMA (w/o encl)

Taylor/pj 5/25/86

OFFICIAL RECORD COPY

DL SPRINGFIELD MED - 0002.0.0 04/30/86