Docket Nos. 50-443

Public Service of New Hampshire ATTN: Mr. Robert J. Harrison President and Chief Executive Officer P. O. Box 330 Manchester, New Hampshire 03105

Gentlemen:

Subject: Inspection Report No. 50-443/86-31

This refers to the routine safety inspection conducted by Mr. Peter C. Wen of this office on June 2-6, 1986, at the Seabrook Station, Unit I, of activities authorized by NRC License No. CPPR-135 and to the discussions of our findings held by Mr. Wen with Mr. D. G. McLain of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:
Lee H. Bettenhausen

Stewart D. Ebneter, Director
Division of Reactor Safety

Enclosure: NRC Region I Inspection Report Number 50-443/86-31

cc w/encl:
John DeVincentis, Director, Engineering and Licensing
William B. Derrickson, Senior Vice President
Warren Hall, Operational Services Supervisor
Donald E. Moody, Station Manager - Seabrook Station
Gerald F. McDonald, Construction QA Manager
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of New Hampshire

JE01

DEFICIAL RECORD COPY

IR SB 86-31 - 0001.0.0 06/24/86

bcc w/encl: Region I Docket Room (with concurrences) Management Assistant, DRMA (w/o encl) T. C. Elsasser, Chief, PB#3C, DRP

/ Wen/gcb 1/3/86 RICHEST FORTH

M:015 Bettenhausen

OFFICIAL RECORD COPY

IR SB 86-31 - 0001.1.0 06/24/86