

Point Beach Nuclear Plant 6610 Nuclear Rd., Two Rivers, WI 54241

(920) 755-2321

NPL 98-0086

February 13, 1998

Document Control Desk
U.S. NUCLEAR REGULATORY COMMISSION
Mail Station P1-137
Washington, D. C. 20555

Ladies/Gentlemen:

DOCKETS 50-266 AND 50-301
LICENSEE EVENT REPORT 98-004-00
REACTOR COOLANT PUMP LUBE OIL COLLECTION SYSTEM
DESIGN NONCONFORMANCE WITH APPENDIX R SECTION III O
POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

Enclosed is Licensee Event Report 98-004-00 for Point Beach Nuclear Plant, Units 1 and 2. This report is provided in accordance with 10 CFR 50.73(a)(2)(ii)(B), "a condition that was outside the design basis of the plant." This report describes the discovery that reactor coolant pump lube oil collection systems did not fully comply with the prescriptive requirements of 10 CFR 50 Appendix R Section III.0.

New commitments within the report are indicated in italics.

If you require additional information, please contact us.

Sincerely,

Douglas F. Johnson

Manager,

Regulatory Services & Licensing

Enclosure

cc: NRC Resident Inspector

NRC Regional Administrator

**PSCW** 

INPO Support Services

9802190178 980213 PDR ADDCK 05000266 S PDR

IEas/