

EVALUATION RESEARCH CORPORATION

CONTROLLED COPY  
CONTROL NO. DF-001

COMANCHE PEAK RESPONSE TEAM

QUALITY INSTRUCTION FOR ISSUE-SPECIFIC ACTION PLAN ISAP-VII.c

CHANGE NOTICE: 001


INSTRUCTION NO.: QI-049

REVISION NO.: 1

ISSUE DATE: 04/03/86


REINSPECTION OF LARGE BORE PIPE WELDS/MATERIAL

The QI identified above is hereby changed  
as shown on the attached page of this notice.

Prepared by:  Date: 4/02/86

Approved by: Albert A. Patterson Date: 4/2/86  
Issue Coordinator

Approved by: E. C. Baiada Date: 4/2/86  
On-Site QA Representative

Approved by:  Date:       
QA/QC Review Team Leader

8607170119 860711  
PDR ADDCK 05000445  
A PDR

1. Change Attribute 1.J ID and Location to read as follows:

Verify that the weld identification and location are per the drawing and applicable design documents.

NOTE 1: No dimensional checks are required.

NOTE 2: When weld identification is not physically obtainable (i.e., not marked, covered, illegible, etc.) verification shall be made by location only, and shall be noted as such in the Remarks column of the Checklist.