

Florida Power

CORPORATION
Crystal River Unit 3
Docket No. 50-302

December 10, 1997
3F1297-09

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555-0001

Subject: LICENSEE EVENT REPORT (LER) 50-302/97-041-00

Dear Sir:

Please find the enclosed Licensee Event Report (LER) 50-302/97-041-00. This LER discusses a condition where the control complex chiller may be rendered unavailable for a time frame greater than assumed in the calculation for the control complex transient temperature response. This report is being submitted pursuant to 10CFR50.73.

Sincerely,


M. W. Rencheck
Director
Nuclear Engineering and Projects

MWR/pmp
Enclosures

cc: Regional Administrator, Region II
Senior Resident Inspector
NRR Project Manager

9712120095 971210
PDR ADOCK 05000302
S PDR

120005



IE221