

Davis-Besse Nuclear Power Station 5501 North State Route 2 Oak Harbor, Ohio 43449-9760

11

NP-33-98-007-1

Docket No. 50-346

License No. MPF-3

January 27, 1999

United States Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Ladies and Gentlemen:

LER 1998-007, Revision 1 Davis-Besse Nuclear Power Station, Unit No. 1 Date of Occurrence - August 24, 1998

Enclosed please find Revision 1 to Licensee Event Report 1998-007, which is being submitted to provide additional information regarding the corrective actions taken for the subject occurrence. The changes are marked with a revision bar in the margin. Please destroy or mark superseded on previous copies of the LER. This LER is being submitted in accordance with 10CFR50.73(a)(2)(i)(B) and 10CFR50.73(a)(2)(v)(D).

Very truly yours,

H Jash

James H. Lash Plart Manager Davis-Besse Nuclear Power Station

GMW/dlc

Enclosure

cc: Mr. James E. Dyer Regional Administrator USNRC Region III

> Mr. Kevin S. Zellers 100018 Acting DB-1 NRC Senior Resident Inspector

Utility Radiological Safety Board

9902100288 990127 PDR ADOCK 05000346 5 PDR