

Clay C. Warren Chief Operating Officer

> December 11, 1997 WO 97-0134

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Station P1-137 Washington, D. C. 20555

Subject: Docket No. 50-482: Licensee Event Report 97-015-01

## Gentlemen:

The attached supplemental Licensee Event Report (LER) 97-015-01 documents that a viola of Technical Spec fications occurred regarding required Inservice Inspection. T-3 examinations of the pressurizer safety valves. This event is being reported pursuant to 10 CFR 50.73(a)(2)(i)(B).

If you should have any questions regarding this submittal, please contact me at (316)  $_364-8831$  Extension 4485, or Mr. Mr. Michael J. Angus at extension 4077.

Very truly yours,

Clay C. Warren

CCW/jad

Attachment

cc: W. D. Johnson (NRC), w/a

E. W. Merschoff (NRC), w/a

J. T. Ringwald (NRC), w/a

K. M. Thomas (NRC), w/a

IEDO",

9712180041 971211 PDR ADOCK 05000482 PDR

