



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

July 28, 1986

Mr J G Keppler
Regional Administrator - Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Response to IE Bulletin 86-02

In response to IE Bulletin 86-02, "Static O-Ring Differential Pressure Switches", there are no SOR Model 102 or 103 differential pressure switches installed (or planned) as safety related electrical equipment at this facility.

Please contact us if you have any questions about this response.

C E Larson
Vice President Nuclear Generation

CEL/MMV/dab

c: NRR Project Manager, NRC
Resident Inspector, NRC
Document Control Desk, NRC
G Charnoff

8608050081 860728
PDR ADOCK 05000263
Q PDR

IE 1
JUL 31 1986

UNITED STATES NUCLEAR REGULATORY COMMISSION

NORTHERN STATES POWER COMPANY

MONTICELLO NUCLEAR GENERATING PLANT

Docket No. 50-263

RESPONSE TO IE BULLETIN 86-02

Northern States Power Company, a Minnesota corporation, by this letter dated July 28, 1986 hereby submits the response to IE Bulletin 86-02, "Status O-Ring Differential Pressure Switches", for the Monticello Nuclear Generating Plant.

This letter contains no restricted or other defense information.

NORTHERN STATES POWER COMPANY

By


C E Larson

Vice President, Nuclear Generation

On this 28th day of July, 1986 before me a notary public in and for said County, personally appeared C E Larson, Vice President, Nuclear Generation, and being first duly sworn acknowledged that he is authorized to execute this document on behalf of Northern States Power Company, that he knows the contents thereof and that to the best of his knowledge, information and belief, the statements made in it are true and that it is not interposed for delay.



