

James A. FitzPatrick  
Nuclear Power Plant  
PO. Box 41  
Lycoming, New York 13093  
315 342.3840



Radford J. Converse  
Resident Manager

July 28, 1986  
JAFP-86-0633

U.S Nuclear Regulatory Commission  
Region 1  
631 Park Avenue  
King of Prussia, PA 19406

ATTENTION: DR. THOMAS MURLEY, REGIONAL ADMINISTRATOR

SUBJECT: JAMES A. FITZPATRICK NUCLEAR POWER PLANT  
RESPONSE TO IE BULLETIN NO. 86-02:  
STATIC "O" RING DIFFERENTIAL PRESSURE SWITCHES

Dear Sir:

The review conducted by the Authority in response to IE Information Notice 86-47 determined that no Static "O" Ring (SOR) differential pressure switches are installed in safety related systems. Another review as a result of this Bulletin concluded that no such switches are installed, or planned for installation in systems important to safety (as defined in 10 CFR 50.49(b)). This completes the Authority's actions in response to Bulletin No. 86-02 for the FitzPatrick plant.

If you have any questions, please contact Mr. J. Flaherty of my staff.

A handwritten signature in cursive script, appearing to read 'R. Converse'.

RADFORD J. CONVERSE  
RESIDENT MANAGER

State of New York  
County of Oswego

Subscribed and sworn to before  
me this 28 day of July 1986.

A handwritten signature in cursive script, appearing to read 'Donnie S. Bastian'.

Notary Public State of N.Y.  
June 30, 1988

cc: W. Fernandez 4857051  
V. Walz  
RMS  
DCC

8608220291 860728  
PDR ADOCK 05000333  
Q PDR

IE: 11  
/10