

582

RELATED CORRESPONDENCE

ISHAM, LINCOLN & BEALE
COUNSELORS AT LAW

DOCKETED
USNRC

EDWARD S. ISHAM 1872-1902
ROBERT T. LINCOLN 1872-1889
WILLIAM G. BEALE 1885-1923

THREE FIRST NATIONAL PLAZA
CHICAGO, ILLINOIS 60602
TELEPHONE 312 558-7500
TELEX 2-5288

'86 SEP -4 10:12

19 S. LASALLE STREET
CHICAGO, ILLINOIS 60603
312 558-5500

INCLUDING REUBEN & PROCTOR
BY MERGER

OFFICE OF SECRETARY
DOCKETING BRANCH
1150 CONNECTICUT AVENUE, N.W.
SUITE 1100
WASHINGTON, D.C. 20036
202 833-9730

TO CALL WRITER DIRECT
(312) 558-

BY MESSENGER

September 2, 1986

Robert Guild, Esq.
Business and Professional People
for the Public Interest
109 North Dearborn Street
Suite 1300
Chicago, Illinois 60602


Re: In the Matter of Commonwealth Edison
Company (Braidwood Station, Units 1 and 2),
Docket Nos. 50-456 and 50-457

Dear Bob:

Enclosed are Bates stamped copies of the engineering drawings referred to in CSR packages CBP-034, CPH-104, and EIN-144. Sargent & Lundy have marked the drawings with red ink to indicate the components which are the subject of the CSR observations. In addition, I enclose additional correspondence related to the implementation of the PTL overinspection program, and revisions 2 through 9 of the PTL site instruction for the overinspection program. Revision 2 was the first revision to be implemented.

In preparation for these hearings S&L has performed engineering evaluations of certain items that were declared out of scope for purposes of the CSR. Commonwealth Edison has not relied on those evaluations in its rebuttal testimony, but they are available for your review, upon reasonable notice, at S&L's offices in Chicago.

Sincerely,



Philip P. Steptoe

8609050154 E:60902
PDR ADOCK 05000456
G PDR

PPS:es

enc.

cc Service List (w/out enclosures)

DSO 3