

Georgia Power Company
Route 2, Box 299A
Waynesboro, Georgia 30830
Telephone 404 554-9961
404 724-8114

Southern Company Services, Inc.
Post Office Box 2625
Birmingham, Alabama 35202
Telephone 205 870-6011



Vogtle Project

April 28, 1986

Director of Nuclear Reactor Regulation
Attention: Mr. Youngblood
PWR Project Director
Division of PWR I
U. S. Nuclear Regulatory Commission
Washington, D.C.

File: X6BK10
Log: GN-885

REF: (1) Required Actions Based on Generic Implications of Salem ATWS
Events (Generic Letter 83-28)
(2) Letter Number GN-276 Dated November 8, 1983

NRC DOCKET NUMBERS 50-424 AND 50-425
CONSTRUCTION PERMIT NUMBERS CPPR-108 AND CPPR-109
VOGTLE ELECTRIC GENERATING PLANT - UNITS 1 AND 2
GENERIC LETTER 83-28

Dear Mr. Denton:

In the above referenced letter Number 2 GPC stated that for item 4.1, concerning reactor trip system reliability, all modifications recommended by the NSSS vendor will be reviewed to verify that either (1) the modification has been implemented; or (2) a written evaluation of the technical reasons for not implementing the modification will be prepared.

This letter is to inform you that the under voltage trip assemblies in the reactor trip switchgear circuit breakers have been replaced at the Vogtle Electric Generating Plant. This modification was recommended by Westinghouse.

Should you have any questions, please inquire.

Sincerely,

J. A. Bailey
Project Licensing Manager

JAB/sm
Enclosure
xc: List attached.

8605020173 860428
PDR ADOCK 05000424
A PDR

A055
1/0

Director of Nuclear Reactor Regulation
April 28, 1986
Page 2

File: X6BK10
Log: GN-885

xc: R. E. Conway
R. A. Thomas
J. E. Joiner, Esquire
B. W. Charchill, Esquire
M. A. Miller (2)
B. Jones, Esquire

G. Bockhold, Jr.
D. C. Teper
W. C. Ramsey
NRC Resident Inspector
L. T. Gucwa
Vogtle Project File

0457V