

APPENDIX A

NOTICE OF VIOLATION

Vermont Yankee Nuclear Power Corporation
Vermont Yankee Nuclear Power Station
Vernon, Vermont

Docket No. 50-271
License No. DPR-28

During an NRC inspection conducted on July 1 - August 4, 1986, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions", 10 CFR Part 2, Appendix C (Enforcement Policy 1986), the violation is listed below:

Technical Specification 4.4.c requires that the boron concentration of the liquid poison tank in the Standby Liquid Control System be determined following any addition of water or boron to the tank.

Contrary to the above, following the addition of water to the liquid poison tank on July 8, and on July 15, 1986, no analysis of the tank boron concentration was performed until an NRC review of the activities identified the deficiencies.

This is a Severity Level V Violation (Supplement I.E.)

Pursuant to the provisions of 10 CFR 2.201, Vermont Yankee Nuclear Power Corporation of Vernon, Vermont, is hereby required to submit to this office within 30 days of the date of the letter transmitting this Notice, a written statement of explanation in reply including: (1) the reason for the violation, if admitted; (2) the corrective steps which have been taken and the results achieved; (3) the corrective steps that will be taken to avoid further violations; and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extend your response time.

8609230229 860916
PDR ADOCK 05000271
PDR
Q