NRC Form 591			U.S. NUCLEAR REGULATORY COMMISSION
(12-81) 10 CFR 2.201 DESIGNATED OR	IGINAL SAFETY I	NSPECTION	
Certified By: Branda	PlatchdK		87-01
1. LICENSEE		2. REGIONAL OFFICE	
Shield Sources, India 2 PENNSYlVANIA AVENUE MALVERN, PENNSYLVANIA 19355		U.S. Nuclear Regulatory Commission Region I 631 Park Ave. King of Prussia, PA 19406	
DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION
	87-2361	60-01G	MARCH 5, 1987
0 30 = 2160 2	97 00		11/11-011 -
and representative records, interviews, with per	sonnel, and observations by the iolations were observed. have taken to correct the violat stivities, as checked below, were which is required to be posted in a	inspector. The findings a ions identified during the in violation of NRC requi accordance with 10 CFR	last inspection. We have no further questions on irements.
C		License Co	of sealed sources were not performed at the proper andition Number
10 CFR		or License Condition Nun	
E. Documents were not properly posted F. Reports or notifications of with 10 CFR			mber were not made in accordance
· · · · · · · · · · · · · · · · · · ·		RETURN ORIGIN REGION I	NAL TO JE:07
В70330038 REG1 LIC30 37-23660-0	1 870305 D16 PDR		
hereby state that within 30 days the actions d This statement of corrective actions is made in the NRC. SIGNATURE - LICENSEE	lescribed by me to the inspector accordance with the requiremen DATE	Marlene	he violations identified in the items checked above. wither response will be submitted unless required b Taylor 3/5/6 E TARC INSPECTOR JOATE