




PHONE 234-2433

BOX 535

CASPER, WYOMING 82602

June 13, 1986

Richard L Bangart, Acting Chief
Radiological and Safeguards Program Branch
Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Re: License 49-12992-01
Docket 30-06811/86-01

Dear Mr. Bangart;

Responsive to your letter of May 16, 1986 please be advised we had mailed the missing certificates of approval on the 7A containers by letter dated May 6, 1986. Apparently our letters crossed in the mail. In the event these certificates did not actually get to your desk, I am enclosing a copy of my transmittal letter and a second copy of the certificates so your file will be complete. I believe this satisfies the violation set forth in paragraph 2 of the NOTICE OF VIOLATION. If this assumption is not correct, please advise and we will respond to your further direction.

At the time of the inspection, our meetings with D. Blair Spitzberg resulted in the joint determination that in each of the instances wherein the manifest was lacking in noting the results of the job site survey that the survey had actually been run and the operator had not recorded the results in the manifest. It was our understanding the inspectors were convinced the situation had been corrected by discussions with our operating personnel. Due to the fact that the issue remains an outstanding issue, we have decided to notify each employee that the record must be completed each time the survey is run. Accordingly we prepared a memo (copy enclosed) which we distributed to each employee as an attachment to their payroll check. This is believed to satisfy due diligence in correcting the substance of paragraph 1 of the NOTICE OF VIOLATION.

We have made a serious effort to resolve all the issues that resulted from the 1986 inspection and believe all the issues have been resolved. If you feel additional matters are unresolved please advise.

Sincerely,

T. W. Morton, Vice-President

8607070317 860702
REG4 LIC30
49-12992-01 PDR

cc: Mr. Jack Whitten
Mr. D. Blair Spitzberg

IC 100/86

NOTICE OF ALL EMPLOYEES

DURING A RECENT INSPECTION OF OUR FACILITIES AND RECORDS BY THE NUCLEAR REGULATORY COMMISSION THE INSPECTORS FOUND INCOMPLETE RECORDS RELATING TO OUR WELL SITE RADIOACTIVITY SURVEYS.

THE NRC INVESTIGATION REVEALED THE SURVEYS HAD BEEN RUN AS REQUIRED HOWEVER THE OPERATOR NEGLECTED TO MAKE THE REQUIRED SKETCH OF THE AREA AND RECORD THE RADIATION LEVELS ON THE MANIFEST.

IT IS IMPERATIVE EACH TIME A JOB IS PERFORMED USING A RADIOACTIVE SOURCE OR A RADIOACTIVE TRACER A SKETCH OF THE WELL SITE TOGETHER WITH RECORDED DATA OF PRE AND POST JOB RADIATION LEVELS AT THE SITE BE PREPARED AND MAINTAINED AS PART OF OUR PERMANENT RECORDS. FAILURE TO COMPLY WITH THIS REQUIREMENT MAY RESULT IN TERMINATION OF YOUR EMPLOYMENT!