Docket No. 030-21269

License No. 37-20856-01

C.P.U.P
OB GYN Presbyterian Medical Office Building ATTN: Patricia Curnyn
Administrator
Suite 220
51 North 39th Street
Philadelphia, Pennsylvania 19104

Gentlemen:

Subject: Inspection No. 030-21269/86-01

This refers to your letter dated August 25, 1986, in response to our letter dated August 4, 1986.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

In your letter you have indicated that you have arranged with a local service to provide a leak test of your sealed source should you require this service. In an aplication dated May 20, 1985 you provided this office with the name of an NRC approved leak test service and leak test kit. We expect that this is the leak test service and leak test kit to which you refer in your letter dated August 25, 1986. If our understandings differ from yours please respond to this office in writing.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:

John E. Glenn

John E. Glenn, Ph.D, Chief

Nuclear Materials Safety Section B,

Division of Radiation Safety

and Safeguards

cc:
Public Document Room (PDR)
Nuclear Safety Information Center (NSIC)
Commonwealth of Pennsylvania

8611110459 861107 REG1 LIC30 37-20856-01 PDR

OFFICIAL RECORD COPY

RL CPUP 86-01 - 0001.0.0 10/16/86 C.P.U.P OB GYN Presbyterian Medical Office Building

2

bcc:

Region I Docket Room (w/concurrences)

RI: DRSS Jensen/gcb Glenn

RI:DRSS

11/1/86 / 11/3/86