APR 2 1 1987

Docket No. 50-318

License No. DPR-69

Baltimore Gas and Electric Company ATTN: Mr. J. A. Tiernan Vice President Nuclear Energy P.O. Box 1475 Baltimore, Maryland 21203

Gentlemen:

Subject: NRC Inspection Report No. 50-318/87-07

An unannounced occupational radiation protection inspection at the Calvert Cliffs Unit 2 facility was conducted on March 23-27, 1987. The implementation of radiological controls during the outage was inspected.

The specific areas examined during the inspection are identified in the enclosed inspection report and included the following: external exposure and personal dosimetry, internal exposure control and assessment, control of radioactive materials and contamination, radiological surveys, monitoring, and ALARA.

Within the scope of this inspection, no violations were identified. No reply to this letter is required. Your cooperation with us is appreciated.

Sincerely,

Thomas T. Martin, Director
Division of Radiation
Safety and Safeguards

Enclosure: NRC Region I Inspection Report No. 50-318/87-07

cc w/encl:
M. Bowman, General Supervisor, Technical Services Engineering
Thomas Magette, Administrator, Nuclear Evaluations
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of Maryland (2)

B704290141 870421 PDR ADDCK 05000318 PDR PDR

1/1

bcc w/encl:
Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o encl)
Section Chief, DRP
M. McBride, RI, Pilgrim
T. Kenny, SRI, Salem
S. McNeil, LPM, NRR
Robert J. Bores, DRSS

RI:DRSS McFadden/ejr

4/20/87

DRSS Shanbaky

4/20/87

DRSS Bellamy

4/2/87

OFFICIAL RECORD COPY

IR CC 87-07 - 0002.0.0 04/14/87