



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

DMB

November 4, 1985

Mr. James G. Keppler
 Regional Administrator
 U. S. Nuclear Regulatory Commission
 Region III
 799 Roosevelt Road
 Glen Ellyn, IL 60137

SUBJECT: Braidwood Station Units 1 and 2
 10 CFR 50.55(e) No. 84-16 Interim Report
 ASME Material Procurement Documentation
NRC Docket Nos. 50-456/457

- References (a): D. H. Smith letter to J. G. Keppler dated October 2, 1984.
- (b): D. H. Smith letter to J. G. Keppler dated November 28, 1985.
- (c): D. H. Smith letter to J. G. Keppler dated February 8, 1985.
- (d): D. H. Smith letter to J. G. Keppler dated April 12, 1985.
- (e): A. D. Miosi letter to J. G. Keppler dated August 2, 1985.

Dear Mr. Keppler:

The above references provided information concerning a potential deficiency reportable pursuant to 10 CFR 50.55(e) regarding the adequacy of ASME Material procurement Documentation at our Braidwood Station. The purpose of this letter is to provide an updated status of the corrective actions taken to resolve this issue. This letter is considered to be a Interim Report.

As previously reported, of the estimated total 4300 heat/lot numbers, an estimated 2200 required additional documentation from the manufacturer/supplier or corrective action to associated records. At this time 95% of these 2200 heat/numbers have been resolved. An estimated 377 of the total heat/lot numbers require some additional corrective action to bring the documentation into conformance with ASME Section III requirements. This additional corrective action has been completed for approximately three quarters of the documentation. Commonwealth Edison Company is

8511140219 851104
 PDR ADDCK 05000456
 S PDR

NOV 5 1985


TE 27

presently working on the remaining documentation in order to complete the corrective action. It is estimated the entire review effort is approximately 98% complete.

It is anticipated that a final report will be submitted in January, 1986 indicating the results of the corrective action.

Please address any questions that you or your staff may have concerning this matter to this office.

Very truly yours,



A. D. Miosi
Nuclear Licensing Administrator

/klj

cc: NRC Resident Inspector - Braidwood

Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

0852K