## FEGUARDS INFORMATION

JAN 2 9 1987

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Joe Williams, Jr. Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

## Gentlemen:

This refers to the routine safeguards inspection conducted by Mr. B. Drouin of this office on January 5-9, 1987, of activities at Davis-Besse Nuclear Power Station authorized by NRC Operating License No. NPF-3, and to the discussion of our findings with Mr. D. Saunders and other members of your staff at the conclusion of the onsite inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the enclosed Notice. The inspection showed that action had been taken to correct the identified violation and to prevent recurrence. Our understanding of your corrective actions are described in Section 5 of the enclosed inspection report. Consequently, no reply to the violation is required and we have no further questions regarding this matter at this time.

We acknowledge the significant accomplishments and new initiatives that have occurred in the security program since the last inspection. We encourage the continued Toledo Edison Company corporate and plant support to the security program. We realize that the support has made a significant contribution to the overall effectiveness of the security program.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Part 73, Title 10, Code of Federal Regulations, Section 73.21(c)(2). This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, the enclosure ( John KIT to this letter and our report of this inspection will not be placed in the NRC Public Document Room.

8702060513 870129 PDR ADOCK 05000346

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled

## SAFEGUARDS INFORMATION

Toledo Edison Company

2

JAN 2 9 1987

We will gladly discuss any questions you have concerning this inspection.

Sincerely.

W. L. Axelson, Chief Nuclear Materials Safety and Safeguards Branch

Enclosures:

Notice of Violation
 Inspection Report
 No. 50-346/87002(DRSS)
 (UNCLASSIFIED SAFEGUARDS INFORMATION)

cc w/enclosures: L. Storz, Plant Manager IE File IE/DI/ORPB IE/ES NMSS/SGPL NRR/PWR-B/SSPB

cc w/enclosures, w/o
 UNCLASSIFIED SAFEGUARDS
 INFORMATION:
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert H. Quillin, Ohio
Department of Health
State of Ohio, Public
Utilities Commission

RIII
Drouin/nma

RIII Weed DeFayette

RIII

AXETSON
Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

SAFEGUARDS INFORMATION