Refer: 10CFR50.54(a)(3)



317 BARONNE STREET • P. O. BOX 60340 NEW ORLEANS, LOUISIANA 70160 • (504) 595-3100

May 1, 1987

W3P87-1028 A4.05 OA

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Subject: Waterford 3 SES

Docket No. 50-382 License No. NPF-38

Updated Quality Assurance Program

Reference: NRC Region IV letter dated 3/19/87, J.E. Gagliardo to

J.G. Dewease (LP&L).

This is in reply to the request of the referenced letter. LP&L provides the following information relative to the NRC concern from review of the updated QA program in the December 11, 1986 submittal of the FSAR first update pursuant to 10CFR50.71(e).

The proposed exception deals with the testing of aggregate used in seismic category concrete. Seismic concrete placements made at Waterford have implemented the Regulatory Guide as previously committed to by LP&L and accepted by the NRC.

We recognize that the proposed exception to Regulatory Guide 1.94, Rev. 1, April 1976, can be interpreted to be a lessening of our commitment to the Regulatory Guide as previously accepted by the NRC. The failure to address this proposed change in our submittal as a possible lessening of a commitment is being addressed to preclude recurrence.

Notwithstanding the foregoing information, and in recognition that there are no modifications planned for Waterford 3 at this time which would require seismic category concrete, LP&L herewith withdraws the proposed exception and will continue to implement Regulatory Guide 1.94, Revision 1, April 1976 as previously accepted by the NRC.

8705060104 870501 PDR ADOCK 05000382 P PDR

Nuclear Safety and

Very truly yours,

Regulatory Affairs Manager

KWC:GEW:ssf

cc: R.D. Martin - NRC Region IV, J.A. Calvo - NRC-NRR,

J.H. Wilson - MRC-MRR, MRC Resident Inspectors Office,

E.L. Blake, W.M. Stevenson

IE43