

UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

August 18, 1997

Dr. Daniel B. Bullen, Facility Director Mechanical Engineering Department lows State University 2025 H.M. Black Engineering Building Ames, Iowa 50011-2160

SUBJECT: ROUTINE SAFETY INSPECTION REPORT NO. 50-116/97201(DRPM) AND

NOTICE OF VIOLATION

Dear Dr. Bullen:

This refers to the inspection conducted on July 21-25, 1997 at the UTR-10 Argonaut Reactor. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation. The violation is of concern because of the apparent failure to properly assure, at specified frequencies, that certain safety systems were operable as required prior to reactor operation.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

Droi"

9708220218 970818 PDR ADOCK 05000116 G PDR

226030





Dr. Daniel B. Bullen

. 2 .

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

Two non-cited violations were also identified during this inspection.

Sincerely,

Original signed by Marvin Mendonca, Acting Director Non-Power Reactor and Decommissioning Project Directorate, Division Reactor Programs Management Office of Nuclear Reactor Regulation

Docket No. 50-116 License No. R-059

- Enclosure: 1. Notice of Violation
 - 2. Inspection Report

No. 50-116/97201(DRPM)

DOCUMENT NAME: G:\SECY\MENDONCA\I-50116

DISTRIBUTION:

Docket File 50-116

PUBLIC

Region III

MSlosson

SWeiss

PDND r/f

MMendonca

CBassett, RII

OGC (015-B-18)

EHylton

BJones (c/ltr. only)

TDragoun, RI

PDND:PM BUO - Milliandonca

8 11/97

PDND:LA EHylton

/ /97

TBurdick, RIII

SWeiss M Mendan

OFFICIAL RECORD COPY