

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

April 18, 1986

Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323


Subject: RII:SJV
Catawba Nuclear Station
50-414/86-08

Dear Dr. Grace:

In order to facilitate your review of our response to Violation No. 50-414/86-08-02, dated April 9, 1986, we are transmitting herewith copies of certain documents which were referenced in our response.

Attachment 1 is our letter of November 20, 1984 to your office, which transmitted Duke Power Company's evaluation of certain inspector identified pipe support discrepancies. Attachment 2 is a Duke Power Company Document entitled "Quality Assurance Assessment of Construction Adequacy-IE Bulletins 79-02 and 79-14", which consists of a review and assessment of Catawba's compliance with these two Bulletins as they pertain to construction.

Very truly yours,



Hal B. Tucker

LTP:slb

Attachments

xc: NRC Resident Inspector
Catawba Nuclear Station

8605050268 860418
PDR ADOCK 05000414
Q PDR

1/1 IE01