



Nebraska Public Power District

COOPER NUCLEAR STATION
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321
TELEPHONE (402)825-3811
FAX (402)825-5211

NLS970147
August 25, 1997

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555-0001

Gentlemen:

Subject: Inservice Inspection Summary Report
Cooper Nuclear Station, NRC Docket 50-298, DPR-46

Reference: 1. ASME Section XI, 1989 Edition

In accordance with the provisions of Reference 1, The Nebraska Public Power District (District) hereby submits the Inservice Inspection Summary Report for the Spring 1997 Refueling Outage at Cooper Nuclear Station. This report includes the Owner's Report for Inservice Inspections and the Owner's Report for Repairs and Replacements. Also included are the results of augmented examinations of the RPV internal Core Spray piping performed in accordance with the Boiling Water Reactor Vessel Internals Project guidelines, BWRVIP-18.

Should you have any questions concerning this matter, please contact me.

Sincerely,

P. D. Graham
Vice President - Nuclear

A047
//

/dnm
Attachment

cc: Regional Administrator
USNRC - Region IV

Senior Resident Inspector
USNRC

Senior Project Manager
USNRC - NRR Project Directorate IV-1

NPG Distribution

9708280212 970825
PDR ADOCK 05000298
G PDR



ATTACHMENT 3 LIST OF NRC COMMITMENTS

Correspondence No: NLS970147

The following table identifies those actions committed to by the District in this document. Any other actions discussed in the submittal represent intended or planned actions by the District. They are described to the NRC for the NRC's information and are not regulatory commitments. Please notify the Licensing Manager at Cooper Nuclear Station of any questions regarding this document or any associated regulatory commitments.

| COMMITMENT | COMMITTED DATE OR OUTAGE |
|------------|--------------------------|
| None | N/A |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |