

Carolina Power & Light Company

Robinson Nuclear Plant 3581 West Entrance Road Hartsville SC 29550

Robinson File No: 13510E Serial: RNP-RA/97-0188

SEP 1 8 1997

United States Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-261/LICENSE NO. DPR-23 SUBMITTAL OF REVISION 06 TO THE SECURITY PERSONNEL TRAINING AND QUALIFICATION PLAN

Gentlemen:

In accordance with 10 CFR 50.54 (p)(2) and 50.4(b)(4), enclosed are the original and three copies of Revision 06 to the Security Personnel Training and Qualification Plan (TQP) for the H. B. Robinson Steam Electric Plant (HBRSEP), Unit No. 2. Two copies of the TQP are being provided to the Regional Administrator, NRC Region II. This revision was made effective on July 23, 1997.

Attachment I to this letter provides a summary of the changes made to the TQP. Attachment II provides a description of each change and the justification that the change does not decrease the effectiveness of the TQP. The TQP has been reclassified from safeguards information and is not required to be protected from unauthorized disclosure.

Should you have any questions regarding this matter, please contact Mr. H. K. Chernoff at (803) 857-1437.

Very truly yours,

Denny M. Wilkeron T. M. Wilkerson

Mana_er-Regulatory Affairs


9709230112

Attachments

c: Mr. L. A. Reyes, Regional Administrator, USNRC, Region II (2)

Ms. B. L. Mozafari, USNRC Project Manager, HBRSEP (w/o Attachments)

Mr. B. B. Desai, USNRC Senior Resident Inspector, HBRSEP (w/o Attachments)



United States Nuclear Regulatory Commission Attachment II to Serial: RNP-RA/97-0168

Page 1 of 3

DESCRIPTION OF CHANGES MADE IN REVISION 06 TO THE SECURITY PERSONNEL TOP

Revision 5	Revision 6	Change Description	Justification
1) Cover Sheet Revision No.	Revision No.	The Revision Number of the TQP is changed.	This change is administrative in nature and does not change the intent of the TQP. Therefore, the effectiveness of the TQP is not decreased.
2) Table of Contents	Table of Contents	The Table of Contents was reformatted, reflecting current page numbers of the TQP.	Revision of the Table of Contents is administrative in nature and does not change the intent of the TQP. Therefore, the effectiveness of the TQP is not decreased.
3) Page 2, Section C-1-a	Page 7, Section C-1-a	This change requires that an individual "carry," rather than "have available," an extra pair of corrective lenses."	The requirement for an individual to carry an extra pair of corrective lenses will ensure the individual har an extra pair of lenses more readily available, if needed This change is consistent with the requirements of 10CFR73, Appendix B.
4) Page 6, Section 2-a	Page 9, Section 2-a	Removed the words "As described in the qualification sections of this Plan."	Pemoval of this wording is administrative in nature, and does not change the intent of the TQP. Therefore, the effectiveness of the TQP is not decreased.
5) Page 6, Section 2-b	Page 9, Section 2-b	Changed wording "Member of the Security Force" to "Armed MSF and Central Alarm Station Operator".	The revised wording is administrative in nature, and does not change the intent of the TQP. Therefore, the effectiveness of the TQP is not decreased. This change includes the verbiage from 10CFR73, Appendix B.
6) Page 7, Section 2-C	Page 9 , Section 2-C	Removed the verbiage "conducted within thirty (30) days".	Removing the 30-day time period for administering the practical physical fitness test does not decrease the effectiveness of the TQP, since the participant must demonstrate that he is physically capable of performing the duties required of an armed Member Security Force (MSF).
7) Page 7, Section C-1	Page 9, Section C-1	Physical Fitness qualifications course site changed to a site outside of the protected area. The performance time limits have been made more stringent.	Since the length of the course has remained the same, and the time limits have been changed to reflect a higher standard than that of the previous revision, this change does not decrease the effectiveness of the TQP.
8) Page 10, Section II.	Page 11, Section II	This paragraph has been re- worded for clarity.	The requirements for MSF training and qualification have not been changed. Therefore, the effectiveness of the TQP is not decreased.

United States Nuclear Regulatory Commission Attachment II to Serial: RNP-RA/97-0188

Page 2 of 3

DESCRIPTION OF CHANGES MADE IN REVISION 06 TO THE SECURITY PERSONNEL TQP

Revision 5	Revision 6	Change Description	Justification
9) Page 10, Section II-a.	Page 11, Section II-a	This paragraph has been re- worded for clarity.	The requirements for MSF training have not been changed. Therefore, the effectiveness of the TQP has not been decreased.
10) Page 11, Section II-A-2	Page 11, Section II-A-2	Removed general text describing MSF training program design.	The manner in which individuals are trained and qualified has not changed. The wording that was removed was a re-iteration of the intent of the TQP and added no additional value. Therefore, this change does not decrease the effectiveness of the TQP.
11) Page 12, Section II-A-3	Page 11, Section II-A-2	Renumbered section for consistency. RSEP Manager-Security changed to RNP Superintendent - Security, or his designated representative.	Since this change reflects page re-numbering, and a title change, it is considered administrative in nature, and does not change the intent of the TQP. Therefore, the effectiveness of the TQP is not decreased.
12) Page 12, Section II-B-1	Page 11, Section II-B-1	RSEP Manager - Security changed to CP&L Security management.	Since this change reflects a title change, it is considered administrative in nature, and does not change the intent of the TQP. Therefore, the effectiveness of the TQP is not decreased.
13) Page 15, Section III-A	Page 13, Section III-A	Added Number 10. Stress firing added to the weapons training program list.	The addition of stress firing training increases the abilities of individuals participating in weapons training. In addition, this change is consistent with 10CFR73, Appendix B requirements.
14) Page 17, Section III-B-1	Page 14, Section III-B-1	Increased the handgun minimum attainable score from 75% to 80%.	This change increases the performance standards for MSF handgun firing, and therefore training increases the abilities of individuals utilizing handguns. This change is consistent with 10CFR73, Appendix B requirements.
15) Page 22, Section V	Page 17, Section V	Removed Security Chief from the list of included MSF. Removed duties for Secondary Alarm Station Operator. This is covered in the Alarm Station Operator duties.	Elimination of the Security Chief from the list of MSF does not decrease the effectiveness of the TQP. Secondary Alarm Station Operator duties have been incorporated into the Alarm Station Operator position responsibilities. In addition, these changes are consistent with 10CFR73, Appendix B requirements.

United States Nuclear Regulatory Commission Attachment II to Serial: RNP-RA/97-0188 Page 3 of 3

DESCRIPTION OF CHANGES MADE IN REVISION 06 TO THE SECURITY PERSONNEL TQP

Revision 5	Revision 6	Change Description	Justification
16) Page 22, Section V.B.	Page 18, Section V.B.	RSEP Manager - Security changed to CP&L Security Management.	Since this change reflects a title change, it is considered administrative in nature, and does not change the intent of the TQP. Therefore, the effectiveness of the TQP is not decreased.
17) Page 23, Section V.C.	Section V.C.	Records Retention section re- written to agree with 10CFR73 Appendix "B" criteria.	Maintaining records retention requirements consistent with 10CFR73, Appendix B does not decrease the effectiveness of the TQP.
18) Pages I-1 through I-18, Appendix I	Pages 21-36, Appendix I	Appendix reformatted to reflect tasks and performance objectives. Rev. 5 Plan task 1.1 is Task #1 in Rev. 6. Rev. 5 tasks 1.1.1, 1.1.7, and 1.1.9 are Enabling objectives A., B., and C for task #1 in Rev. 6.	This change does not decrease the effectiveness of the TQP because, the tasks have been reformatted. No tasks have been deleted from the TQP.
19) Pages II-1 through II-6, Appendix II	No equivalent pages	Pages deleted which reflected responsibilities analysis of the Manager-Security and Security Chief.	This change does not decrease the effectiveness of the TQP because duties of these Security Force Members reflect a pattern of allowing a person to be tasked to the level necessary to perform the job skills required.
20) Pages II-7 through II-42 Appendix II	Pages 37-62, Appendix II	These pages have been revised to reflect the changes made in Appendix I.	This change does not decrease the effectiveness of the TQP because, the tasks have only been reformatted. No tasks have been deleted.
21) Page III-1 through III-3, Event- Task Identification Saramary	No equivalent pages	This section has been deleted from the Plan.	This change does not decrease the effectiveness of the TQP because the information removed was redundant to information currently contained in Appendix II to the TQP. The event-task identification summary is not required by 10CFR73 Appendix "B."