

ENCLOSURE 2

NOTICE OF DEVIATION

Duke Power Company
Catawba 2

Docket No. 50-414
License No. NPF-52

The following deviation was identified during a Nuclear Regulatory Commission (NRC) inspection conducted on December 26, 1986 - January 25, 1987.

The licensee informed the NRC, in its November 18, 1986 response to a Notice of Violation dated October 20, 1986, that training would be completed on IP/O/A/3890/01 (General Troubleshooting Procedure) by November 30, 1986 and that Section 4.3.10 of MMP -1.0 (Work Request Preparation) would be revised by December 31, 1986 to include additional guidance for planners to list appropriate component procedures when applicable.

Contrary to the above, training of all applicable personnel was not completed by November 30, 1986 and Section 4.3.10 of MMP-1.0 was not revised by December 31, 1986.

Please provide in writing within 30 days of the date of this Notice a description of corrective actions regarding this deviation, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

FOR THE NUCLEAR REGULATORY COMMISSION

Original Signed by
Luis A. Reyes

Luis A. Reyes, Acting Director
Division of Reactor Projects

Dated at Atlanta, Georgia
this 6th day of Feb. 1987

8702190186 870206
PDR ADOCK 05000413
G PDR