

NOTICE OF VIOLATION

Iowa Electric Company

Docket No. 50-331

As a result of the inspection conducted on December 2-5, 9-12, 15-18, 1986, and January 12-16, 1987, and in accordance with "General Policy and Procedures for NRC Enforcement Action," 10 CFR Part 2, Appendix C (1985), the following violations were identified.

1. 10 CFR 50, Appendix B, Criterion V, as implemented by Duane Arnold UFSAR, Section 17.2.5, requires that activities affecting quality be prescribed by documented instructions and procedures and accomplished in accordance with those instructions and procedures.

Contrary to the above, the licensee failed to perform use history evaluations for measuring and test equipment found out of calibration as required by Procedure No. MD-017.

This is a Severity Level IV violation (Supplement I).

2. 10 CFR 50, Appendix B, Criterion VI, as implemented by the Duane Arnold UFSAR, Section 17.2.6.1, requires that documents, including changes, are reviewed for adequacy, are approved for release by authorized personnel, are distributed to and used at the locations where the prescribed activities are performed, and are controlled.


Contrary to the above, the licensee had not maintained a completed and up-to-date set of Piping and Instrumentation Diagrams (P&ID's) in the control room for use by the reactor operations personnel.

This is a Severity Level V violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

FEB 18 1987

Dated _____



J. J. Harrison, Chief
Engineering Branch

8702250251 870218
PDR ADOCK 05000331
PDR
Q