

Illinois Power Company Clinton Power Station P.O. Box 678 Clinton, IL 61727 Tel 217 935-5623 Fax 217 935-4632

John G. Cook Seriior Vice President

U-602851 2C.220

October 28, 1997

Docket No. 50-461

10CFR50.73

Document Contro! Desk Nuclear Regulatory Commission Washington, D.C. 20555

Subject: Clinton Power Station - Unit 1

Licensee Event Report No. 97-025-00

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 97-025-00: Design Deficiency Results in Plant Being Outside Design Basis for a Fire in the Main Control Room Potentially Damaging Valves Required for Safe Shutdown of the Plant. This report is being submitted in accordance with the requirements of 10CFR50.73. Commitments made in this Licensee Event Report are:

- Analyze and modify, as required, each of the affected motor operated valve (MOV) circuits to ensure that a fire in the Main Control Room will not affect the ability of the valve to operate so that the capability to achieve safe shutdown is assured.
- Revise the applicable engineering review standards to require that changes for safe shutdown electrical circuits be reviewed against the criteria in Information Notice 92-18.
- Perform a review of components, other than MOVs, for applicability to the condition described in Information Notice 92-18.

Sincerely yours,

9711040273 971028 PDR ADOCK 05000461 E PDR

00101

G. Cook Senior Vice President

MRS/krk

Enclosure

cc: NRC Clinton Licensing Project Manager
NRC Resident Office, V-690
Regional Administrator, Region III, USNRC
Illinois Department of Nuclear Safety
INPO Records Center