

MAY 13 1987

Docket No.: 50-312

Mr. J. Carl Andognini
Chief Executive Officer, Nuclear
Sacramento Municipal Utility District
6201 S. Street
Post Office Box 15830
Sacramento, California 95852-1830

Dear Mr. Andognini:

SUBJECT: RANCHO SECO RESTART REPORT - REQUEST FOR ADDITIONAL
INFORMATION (TAC NO. 61635)

By letter dated December 15, 1986, SMUD submitted the Restart Report for the Rancho Seco Nuclear Generating Station. We have reviewed Section 3.2.4 (Steam Generator Overfill and Flooding of the Main Steam Headers) of the Restart Report and find that we need additional information to complete our review. Please respond to the enclosed request for additional information.

The reporting and/or recordkeeping requirements contained in this letter affect fewer than ten respondents; therefore OMB clearance is not required under P.L. 96-511.

Sincerely,

/s/

George W. Knighton, Director
Project Directorate V
Division of Reactor Projects - III/IV/V
and Special Projects

Enclosure:
As stated

DISTRIBUTION

Docket File 50-312

NRC PDR/L PDR

D. Crutchfield

G. Holahan

J. Lee/R. Weller

OGC-Bethesda

E. Jordan/J. Partlow

ACRS (10)

RAW

DRSP/PDV

RWeller:cd

5/13/87

DRSFA

GWKnighton

5/13/87

T. Marsh

M. Hartzman

G. Kalman

8705290148 870513
PDR ADOCK 05000312
P PDR

OFFICIAL RECORD COPY

Mr. G. Carl Andognini
Chief Executive Officer, Nuclear
Sacramento Municipal Utility District

Rancho Seco Nuclear Generating
Station

cc:

Mr. David S. Kaplan, Secretary
and General Counsel
Sacramento Municipal Utility
District
6201 S Street
P. O. Box 15830
Sacramento, California 95813

Mr. John Bartus
Ms. JoAnne Scott
Federal Energy Regulatory Commission
825 North Capitol Street, N. E.
Washington, D.C. 20426

Thomas A. Baxter, Esq.
Shaw, Pittman, Potts & Trowbridge
2300 N Street, N.W.
Washington, D.C. 20037

Mr. John V. Vinguist
Acting Manager, Nuclear Licensing
Sacramento Municipal Utility District
Rancho Seco Nuclear Generating Station
14440 Twin Cities Road
Herald, California 95638-9799

Mr. Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation Division
Suite 220, 7910 Woodmont Avenue
Bethesda, Maryland 20814

Resident Inspector/Rancho Seco
c/o U. S. N. R. C.
14440 Twin Cities Road
Herald, California 95638

Regional Administrator, Region V
U.S. Nuclear Regulatory Commission
1450 Maria Lane, Suite 210
Walnut Creek, California 94596

Mr. Joseph D. Ward, Chief
Radiological Health Branch
State Department of Health Services
714 P Street, Office Building #8
Sacramento, California 95814

Sacramento County
Board of Supervisors
827 7th Street, Room 424
Sacramento, California 95814

Ms. Helen Hubbard
P. O. Box 63
Sunol, California 94586

REQUEST FOR ADDITIONAL INFORMATION
OTSG OVERFILL AND FLOODING OF THE MAIN STEAM LINES
RANCHO SECO NUCLEAR GENERATING STATION
MECHANICAL ENGINEERING BRANCH
DIVISION OF ENGINEERING AND SYSTEM TECHNOLOGY

1. Provide an evaluation and verification that the design limits for the supports of the steam generator, the "A" main steam line and the "A" main steam bypass line have not been exceeded due to overflow and the injection of the 13000 gallons of water.
2. Provide the results of the detailed examination of the welds and piping of the bypass line currently being performed.