


FOIA-86-894 April 28, 1977 C/7

Mr. James G. Keppler
Director - Region III
U.S. Nuclear Regulatory
Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Subject: Security and Safety Related Allegations

by a Quad-Cities Nuclear Power Station

Contract Security Guard

References: R. L. Bolger letter to James G. Keppler,

dated March 10, 1977

R. L. Bolger letter to James G. Keppler,

dated March 25, 1977

Dear Mr. Keppler:

An investigator employed by Pinkerton's, Inc. was assigned as a security guard at Quad-Cities Nuclear Power Station from March 21 through April 7, 1977. The purpose of assigning the investigator was to determine if allegations by Mr. James E. McKay, a Pinkerton Guard, were credible.

Based on a recommendation by the investigator, Mr. McKay was offered another position by Pinkerton's Inc. and transferred from the station. According to the investigator's reports, Mr. McKay was disliked by all of the station guards and by many of the Commonwealth Edison Company employes at the station. It was the investigator's opinion that Mr. McKay was "a troublemaker and highly over-reactive and imaginative".

The enclosure to the March 10 letter to Mr. Keppler included seven items which were to receive emphasis during the investigation. The following paragraphs are keyed by number to the paragraph of the March 10 report and include the findings of the investigator:

2. The metal detector did not always work properly because it required sensitivity adjustments to detect keys and other small metal objects. Appropriate adjustments are made as necessary and adjustment controls are secured by a lock. Access to the adjustment controls is permitted by the shift supervisor.

8705290318 881222 870527 PDR FOIA MCKAY86-894 PDR

LU CFR 2.790 Information Act, exemptions FOIA- 86-899

Information in this record was deleted in accordance with the Freemom of Information Act, exemptions 3

FOIA- 86-899

- 8. Each time an employe attempted to exit the Protected Area with Company property without appropriate authorization, the employe was required to return to the plant for a property pass.
- 11. The guard filing cabinet was left unlocked at times, but only for several minutes and only if a guard was near by. When the cabinet was not locked after use by a guard, it was brought to the guards attention by a guard sergeant.
- 17. The guard test was found to be well written, difficult and thorough. The investigator suggested some improvements for instructors which are being evaluated by Pinkerton's, Inc. The test is designed to cover the basic guard training, but not all specific station security procedures.
- 23. The investigator was unable to identify any guard at the station who has attempted to sell stolen materials.
- 24. The investigator did not observe any employe depart without turning-in his security badge. There have been no reports of badges taken from the Protected Area since March 10, 1977, when the guards were requested to include such occurrences in the guard report.
- 28. The investigator identified no basis for questioning any guard's integrity because of a large purchase.

Item 21 of the enclosure to the March 10 letter included a statement that station management was evaluating the use of local audible alarms on the Vital Area Doors. The alarms were installed and are providing adequate assurance that the doors are properly closed.


This letter addresses a subject matter exempt from disclosure according to Section 2.790 of the Nuclear Regulatory Commission "Rules of Practice", Part 2, Title 10, Code of Federal Regulations. Consequently, this letter should not be placed in the public document room.

Sincerely,

R. L. Bolger

Assistant Vice President

10 CFR 2.790 Information




Information in this record was deleted in accordance with the Freedom of Information Act, exemptions 3+6 FOIA- 86-894

Memorandum

Subject: Report of Investigation of Allegations by Quad-Cities Nuclear Power Station Gu ... James E. McKay

During the period March 2 through March 8, 1977, an investigation concerning allegations by Mr. McKay was conducted by the following individuals:



Each of the following paragraphs includes a statement of the allegation; a summary of findings; and, if appropriate, corrective action taken:

Papers (drawings and unidentified specifications) were found near the Protected Area fence.

The papers were provided by Mr. McKay and examined. The papers pertain to contractual arrangements, work orders, s construction requests and accounting statements. All of the papers are in excess of five years old and were disposed of following a recent purge of files. None of the papers contains information of significance to the security program. No drawings were included with the papers provided by Mr. McKay.

2. The metal detector does not always work properly. Some of the guards have walked through without detection while carrying a weapon.

The metal detector was checked and found to be operating properly. The sensitivity of the metal detector is set to detect grams of ferrous metal. In a telephone conversation with Mr. McKay on March 3, he explained that the ability of the guards to defeat the metal detector was as a result of repeated efforts and experimentation. Since personnel normally entering the Protected Area are not provided with the opportunity to experiment with the metal detector, this is not considered to be a security weakness. A report of investigation by Pinkerton's, Inc. will include an evaluation of the ability of the guards to defeat the metal detector. PART 2.790(d) INFORMATION 3. The Radiation Portal Monitor is not always working properly.

Two Radiation Portal Monitors are located in the guardhouse. The monitors facilitate rapid egress from the site since the monitors nominally require ten seconds to complete a cycle. Also, some redundancy is provided in the case of a failed component. The monitors have experienced some failures, but not normally both at the same time. If both monitors fail, a Geiger-Mueller counter is available at all times at the guardhouse for radiation check-out purposes. Radiation Chemistry Technicians are on site at all times and are to be called if the monitors fail. During the day shift Monday through Friday, instrument mechanics are available to service the monitors. The NRC recently investigated allegations concerning defective portal monitors and found no evidence of noncompliance.

4. A Commonwealth Edison employe named talks disrespectfully about other employes around the guards.

Mr. does have somewhat of an out-going personality, however this has no security implications.

5. Employes have been observed intentionally abusing dosimeters by throwing them against the window shade and floor of the guardhouse.

A Radiation Chemistry Technician acknowledged such abuse to be of a jovial nature after determining a dosimeter to be inoperative and of no possible further use. The purpose of the abuse was to render the dosimeters "obviously inoperable" so they could not be inadvertently reused.

Corrective Action: The employe has been instructed to discontinue the practice of throwing dosimeters and an alternate method to insure that the dosimeters will not be inadvertently reused has been suggested.

Unauthorized contractors have been observed in Vital Areas.
 No positive action was taken when this was reported.

In accordance with the Security Plan and Procedures, contractors are permitted unescorted access to Vital Areas as required in the performance of their duties. There have been no reports of unauthorized contractor personnel in Vital Areas.

7. A Vital Area door was reported broken and unlocked for several days before a guard was posted.

At 4:00 p.m. on January 27, a Vital Area door was reported damaged. The door, even though damaged, could still be locked. By January 29, the door had not been repaired and had become practically inoperable. Guards were instructed to check the door twice per shift to insure that it was locked. A guard was posted at the door on January 31 and February 1 while the door was being repaired.

8. Rolls of steel, scrap copper and sandpaper have been taken by employes without property passes.

It is suspected that theft of station property by employes and contractors does occur. Theft of small quantities of material is extremely difficult to detect. Presently, no information is available which indicates that any specific employe or contractor is guilty of theft of station property. An investigation by Pinkerton's, Inc. will include an effort to determine if the station guards are knowledgeable of unreported thefts.

9. Employes frequently depart without turning in security badges.

Occasionally an employe will depart the station and inadvertently fail to turn in this security badge. Employes must return security badges to the guardhouse in order to reenter the Protected Area. This is not considered to be a frequent occurrence.

Corrective Action: In order to determine frequency, guards have been instructed to include reports in the daily guard log of employes departing without turning in security badges.

10. A guard had the guard force Vital Area keys at home for 2 or 3 days.

The keys, which were Protected Area gate keys rather than Vital Area door keys, were reported missing and assumed to be lost. The gate locks were exchanged for new locks and new keys were issued. After the locks were changed it was discovered that a guard, who had been on a weekend break, had inadvertently taken the missing keys home with him.

11. Contrary to security procedures, the guard file cabinet is always unlocked.

(: 1

Quad-Cities security procedures do not require that the guard filing cabinet in the guardhouse be locked. This requirement is included in a written procedure for the guards issued by Pinkerton, Inc. An investigation by Pinkerton's, Inc. will include an effort to determine if the filing cabinet is normally unlocked.

12. Employes and contractors are frequently observed in hard hat areas without hard hats.

Enforcement of the OSHA hard hat requirement has at times been difficult, particularly with contractor personnel, however, it does not present a security problem. Recent progress has been made with both station and construction personnel since increased emphasis has been placed on wearing hard hats. Contract specifications contain a statement referencing the hard hat requirement and its implementation.

13. Floor plans of the plant from the guard procedure are missing.

The exact nature of the drawings which may be missing from the guard procedure cannot be determined. At some time in the past, drawings may have been available to the guards which showed the Protected Area, perimeter and gate numbers, or engineering drawings which showed the plant floor plan. Drawings of this type have been widely distributed and if such drawings are missing from the guard procedure, the loss of the drawings does not have a significant adverse affect on the station security program. A set of engineering drawings showing the plant floor plan were located in a desk drawer in the guardhouse.

14. An employe named frequently drives at a dangerously high rate of speed within the Protected Area.

No information pertaining to speeding within the Protected Area is available; however, Mr. has been instructed to insure that he does not exceed safe speeds while operating a vehicle within the Protected Area.

 Engineering drawings were found in an unoccupied, unsecured area.

Engineering drawings of a non-security nature are abundant in administrative areas which at certain times are unoccupied and unsecured. This does not violate the station security plan, nor does it present a security problem.

16. CCTV cameras are frequently inoperative because of weather or because they require maintenance.

At times CCTV cameras are inoperative because of weather or maintenance requirements. Inoperative remote visual monitoring equipment providing surveillance capabilities for the Protected Area is documented by guard reports. When are conducted in accordance with the Security Plan.

17. The qualification test for the guards does not agree with written procedures.

A review of the guard qualification did not reveal areas which are not in agreement with written procedures. This item will receive further evaluation in an investigation by Pinkerton's, Inc.

18. A lot of fish are killed.

in ..

Fish impingement is monitored at the station pursuant to the station's Technical Specifications. Technical Specification Appendix B.2.3.A requires that an inventory of fish entrappment on the intake structure be made twice per week. This information is reported to the NRC in a semi-annual report, "Operation Environmental Monitoring in the Mississippi River near Quad-Cities Station" by Nalco Environmental Sciences. Additionally, the information is reported to the Illinois and Federal Environmental Protection Agencies as a requirement of the Station's NPDES permit.

19. A vehicle was not provided for required guard patrols in extremely cold weather.

Guard patrols are conducted in accordance with the Security Plan and Procedures regardless of the weather conditions. Approximately three months ago an electric car purchased for use by the security force was returned to the vendor for repair. The car was experimental in nature and the malfunction could not be diagnosed or site. The vendor did not progress in the repair of the vehicle, therefore it was retrieved during the week of February 28 through March 4 and repairs are to be undertaken by Commonwealth Edison.

20. The Owner Controlled Area gate # 28 is broken.

Gate # 28, an Owner Controlled Area gate, which is not in the Protected Area barrier, was damaged. A work request to repair the damage was submitted on November 19, 1976 and resubmittal on January 12 and January 26, 1977. The gate is scheduled for repair on March 9.

21. Vital Area doors are frequently found intentionally left open.

A Vital Area door intentionally left open is not considered to be a frequent occurrence. Vital Area doors to the an area isolated from the main building which has a relatively high number of personnel entering and exiting, are the primary problem area. These doors are checked times daily by the Station Security Officer and times per shift by the station security guards. A security education program places emphasis on security by station management at weekly department meetings.

Corrective Action: Station management is evaluating the use of local audible alarms for installation on the Vital Area doors. These alarms would insure personnel awareness of a door which was not properly closed.

22. Doors to the administrative areas are frequently left unsecured.

There is not a security requirement to lock the administrative area doors. The unlocked administrative areas are not Vital Areas.

23. A Pinkerton guard offered to sell stolen motor oil.

not all

No additional information is available concerning sale of stolen property by guards. An investigation by Pinkerton's, Inc. will include an effort to determine if members of the guard force are dealing in stolen property.

24. Employes do not always check-out and check-in for lunch.

The number of employes departing the station at lunch is quite small since only 30 minutes is allowed; therefore, there is no reason to believe that employes slip out unaccounted for. It is the practice of some guards not to file the security badges for the employes departing for lunch in their respective slots since they return after a very short period of time. This item will, however, be included in the investigation by Pinkerton's, Inc.

25. The electric car for the guards was abused and has not been returned for the use of the guards.

The cause of malfunction in the electric car has not been determined. The status of repairs to the car is provided by Item 19.

26. Badge photos: some were expired and not replaced; one guard was photographed in civilian clothes.

The Station Security Office maintains an effective suspense and notification system for insuring that badges are reissued prior to expiration dates. A monthly list of badges which will expire is provided to the guards. The guards verbably notify employes of expiration and if necessary attach notes to the badges. If a badge is not renewed prior to the expiration date it is removed from the badge rack and provided to the Station Security Officer. At times a guard photograph on a security badge may be made with the guard dressed in civilian clothes. This lack of uniformity in badge photographs for guards has not adversely affected station security, however, in the future guard photographs for badges will be taken with the guard wearing a uniform.

27. When Mr. visited the station the guards were jokingly making comments that someone should shoot him.

Mr. These comments may have been made during a recent visit by an Executive Vice President of the Company. Comments of this nature are not condoned, however, we do not believe that a threat exists to the individual or to the security of the station as a result of the comments.

28. One of the guards has recently purchased a new car and a house.

This allegation implies that a guard obtained the money necessary for these purchases through some sort of illegal activity. No information which substantiates illegal activity by members of the guard force is available. However, the investigation by Pinkerton's, Inc. will include an effort to determine if guards are involved in illegal activity.

L. B. Bean

2-24-77 plof6

m.

Enclosed is a small sample (approx 15 pages) of business dicuments found Lying outside along the pwitch yard fine. (datavary) I made nate of these on my 2-22-77 Repet-wars told reat to bather with the jake among the guredo Tues. 2-22-77 was to bomb the CECO pris edent's helicopter. In my book this certainly is no way to yake. Some of CECO and Pinkerton Guerdo should have a torrough back ground Chuk out.

> FOIA-86-894 D/1

Their attitudes and behavior towards work as well as outlook on life in general may reveal some interesting facts induct. Since of them carry very un healthy thoughts. Some should not even be Carryinga gun. profined off Sati That ou alarm Bones would be tested. Sure enough approx 11/2 horres later ht. penistrated our Security Lysten. m. and Me. are besty spendsa friends quest derl of fline in quard Final 12 10 3 hrs at a

boes ME? >> (Shift Engs.) brake in on job. They are 2 of a Kind. This mc Comes down to quant house and talks with Soft about 819 how he puts things own on the rest of CECO Employees. He acts and talks very by what - for tolken, with Sat Buddy Buddy! got. Tells me to Key quit- He Claim, Re Knows thengo going on there that wented really shock one. has almost run our me on 3 occusions While I'm out on patral. He yakes i makes fun of it.

In my apenion he is a Very dangerous person, (scary to be around). I'm murithed, and unpredicable - He hasa bail driving record to go along with his crange way of driving (speeds). Gate 28 has not get been repaired. Coutte patrall. In contain he's The one who smachest itien. Guards recked the 3,000 electric Car that was at their Olopusal. - we no longer have Howe seen PAD men 5 Guards take DOSINISTERS and throw against wall of quand turise - Pock marks on shedes from impact.

Scrap, Copper tubing taken out of plant, stul int @ Told not to Check Clifain Clas i trucks out. VAD Keys list for almost 3 days, -I called Rick 15 kind office and told mys. - The security Lt. was really putout with me of alleny R/I office. File calnut in to be locked at all times inside quaid house - Tregative its your 24 Hours around The Click. I have many more theres listed but will not send at This fine. spent time in breezes baro soris CECO Employees - PRINKIUG.

PART 2,750(4) INTELLIBRIUM

True drinks etc. Dring Buddy, Buddy. The union is Why strong here i has a grad deal of power do well as in-Energh for ner mistys to werk. Sincuely, Jim mcKay P.S. phone is


JJECT: NEW SICK LEAVE POLICY PART 190(2) INFORMACE

has been brought to my attention that the attendence record of this company a disgrace. Due to the lack of consideration of your job with so fine a a pany, as shown by such frequent absenteeism, it has become necessary for us revise some of our policies. The following changes are in effect as of this to:

- CKNESS.... NO EXCUSE. We will no longer accept your doctor's statement as proof;
 We cannot help but feel that if you are able to go to the doctor,
 you are able to come to work.
- ATH....(OTHER THAN YOUR OWN)...This is no excuse. There is nothing you can do for them, and we feel sure that someone else with a lesser position than yours can attend to the arrangements. However, if the funeral can be held in the late afternoon, we will be glad to let you off one hour early, providing that your share of the work is ahead enough to keep the job going in your absence.
- We wish to discourage any thought you may have regarding the need for an operation as we feel that as long as you are employed here, you will need all of whatever is removed. We hired you as you are and to have anything removed would certainly make you loss than what we bargained for.
- however, like a two week notice as we feel that it is your duty to teach someone else your job.
- LSO.... Entirely too much time is being spent in the restroom. In the future, we will follow the practice of going to the restroom in alphabetical order. For instance: Those whose names begin with "A" will go from 8:00 A.M. to 8:05 A.M. and so in. "B" will go from 8:05 A.M. to 8:10 A.M. and so on. If you are unable to go at your time, it will be necessary to wait until the day when your turn comes again.

There are the Johns did take Copies of inside Muchan Plant. He had Consider to detailed Previous of horaline mails potters

PARP 2.790(d) INFORMATION



2. Metal Duteston doesn't work.

1. Papers along fence + PA.

- Metal Dete off one can or could pass though w/G ms or bombs.
- 3. Radiaton Manitars don't work.
- "Coo employees + others go home uf Hi Rud readings Shift Engine M5 ... has let then go.
- 4. More talking derispectfully about guards


The fact they were returned to USE?

6. Unouthoused contractors in

I Union + out side contractors had UA Keyo. Someloody in Printertonis has given NAD keys to outside . DUK. outside contractors had UAD Keys to " Outside contractors coming out of They ray they always tod. Keys. They sthould not to bettere.

> Information in this record was deleted in accordance with the Freedom of Information Act, exemptions 3+6 FOIA- 86-894

* Doors to off gas Filter Hamel.



10. Gd took VA Keys home.

11. Gd Fate Cabinet open

For about 3 days fad the keys at houl. 2/17/2 VAD Keys missing forddays & AFTER. "Apparently had taken them have. " T/5 Locks - They court use to open 6-1 locks but can use "3" key for G-1 Key

12. Hard Hats.

to Had hats not ling wow They could beam something from calif plants:

13. Floor plans from Gd Procedures missing

From QSP. taking floorplans admitted to me he could get asp lad 5 pages missing up Flow chart of Daples. Sill says got there





15 Engineer drawings found

Duies reclasses. Messed me 84 makes

Very close.

Schands 2-3 hrs in GH.

2/21/17 Tappedoff of alam to 4

around 0670 +0750

tunizard lights in Bailer Rom.

16 CCTV Cameras inop.

17. Gd Qualification Tests not in Prouding Dot Review OSP TRNGS. Sans of Egypo melfulous cortiss in G 4 CCTU 2+3 romas aut at a hour tones left seed ice-snow Repair man planis mow what he is doing.

- * SGTS should train grander they don't other gods
- * Misguided Munformed.

18. a lot of fish are RiP'd.

Mot ling recorded.

Al: briotest ->

Records lost.

FISH FIRM FULL W/DOND FISH

Success ment working.

19. Vehile not prouded for Gods in cold weather.


Protestee seeen not working properly at witche flume. "I think this was corrected of GARBAGE RED in QC. to E + DGATE. IT Felmany March + James.

Wastsldto wall rounds in - 40°-60° told to walke ar me orum can. for Patrols "On 3 id day used myouncar, for Patrols "Geto reched elect. Car"


20. OCA Gate "28 broken

Possety auto in bod need of Repair.

21. VA Doors found open



22. Doors to admin areas



24. Employees do not chaut forfund.

* Too many times employees are to ching in + out of Plan 2-3 times not layged.

25 Elect. Can for gols was

" Glowerled elect Can.

26 Badges - expuid anot replaced + gd in cinies.

276 do johning about whooting

Sometimes No BADGES. - left sometable else. " Took Bodges Hone. " Badges in rach that were expire D.

Voke about it NPC + (BO Pres known FAR in advance. Jokshow beleiopen on 2/22/17 THIS IS NOT FUN-4

28 GI hought a new house + car.

Very Layed at nite. Sped in My for 10-15 min at 24 m LUTTER TO PERCY 1 29 CECO+ Prink have had lot of bur to clean up a lot of durageances. 30 Fires him without good cauce. Menertales & FBI mutil after. Ican well enough alone. 32 Union fighting + Dunihung an CEcoproporty. Trued in 3 page report. So did to Turist to total was beat up by 400 5, Welders / bloodied ALLNITE WELDERS DRINKING ON JOD Threats "said "they " were out to get M' Kay Called lecause of thees made against him Theats by MAINT People threatened ! 35 Pischerton Imentigation was a waste of CECO and Penkerton's Inc had about 8 weeks to get things cleared up - or conceed up.

Carried

* Bornoquaphy Hearson.

1 37. Landy room - Yellow clothes not properly cleaned. + ??? thowing contaminated itens accoss soon. Careless in the way they perform duties.

/ 38 Police permitted to take fricams on site.

1 39 QSP Manuel needsupdating.

V 40 Fence Westride - nothigh enough finally CE co fixed it.

41 Scrap (Good) Laying around property.

V 42 LA driestoo much at Bar - Hallfop 597 Too Buppy, Buddy for Sucupity Curposes.


43. (EW reals on Recueulan Pemps 2/12/77 (AGAIN) Outle often This goes on - poor operations MAINT. It looks - MAINT not doing their job as should be. & Rad Lat. 7 stuff Laying #

Hallow near Maint area. 44 Computer Settings on Body Counter IN RAd Room LAB. - TAMPERED WITH - INCORRECT READINGS - Chittering up door way with highly rad tools etc.

(45) BLDGC left open.

Roll min.

someti bugs + some not.



In MAIN

46 SGT metaman at Tw 2 door -

Mech Engier USGUMT. 42 Crack in water FEETS Live & REACTOR UNIT! I maperton is in 7/28/77 also more cracks in reactor Compressor door it seems was Blown 48185 PRESS - SEAL DAMAGES IT SECRS.

Very Supertent of

(48 5/18 + 3/1 Ouit I Refuel Stages for 12/76

FUEL 7EST PROGRAM Broks - Easy access
to the TARE there very important books
also U I Refuel outage (Jange black books)
for Spring 77

Pak Want informed of these

Fish Want informed of these

Good ley Searches

Comera Cardo was nined.

50

V 49 GE had camera inside for 3/25-31

moth 3000 to 20,000 milicers.

5\$ Told not to wite up UADoors open on Fours Put on Price of pater. Ottevise if goes an reports USGUMT Fines (E10 for open doors.

Much Congriss.

57 Vata on Cilhouse floor. 58 Leahour Values Cufthouse Boler room Left Station. 54 Ceridon TW " 1 Floor. 55 Contal loopes in Hz Form open This had to do w/ after he was

56 Manus of Former grunds never lined at such address - neighbors never heard of them B/4 yet weekied

1. Reports on Fright March 77

2. Merer recieved QSP Traing.

3. Donou radevoste.

4.

Frenence QSP- Mener received it Did get had ting. Jimmacky Stalm wer bied to back in Feb. Moletron was hole Theats - undermin 3 times that's why he went to fete. (These little Public.)

The theatened his causer. Seems to be confused with the fitter Public.) 7 Then went & RI FBI out oncheal. a little to reported (TRACKURY 2) they had beat his up M- went to see if day God a Gan but had pipe. REPORTS Hasty-rolled you + was arested. ON DOORS URIAting Ducking a Papaicons. eTC Should be there See geny's note. Snow told him to write report ane. Many times. "Salt" -> SGIT's backed up (CCO not Gds. Outside Contractory were impossition of keys. Informan 77 Right across from Laurdy woon.

Neyhold keys - lust not less Keys. * & People.

Of lest some had Jellow lunges. backon leadge. dropping donimeters . + putting Mener recent QSP TRNG. From Dec 76 to april 77. Did Get Rad TRAG. told him He (mckey) has shook up Maint. dept. Kup how left site > lost. When he reported
May have been >CECO employees guing heys to Contactors to make
there

December 76 to HTKNE 11.

9

Information provided by Mr. McKay.

- 1. Papers (drawings and unidentified specifications) were found along the Protected Area fence. These were mailed to D. Rossin.
- 7 2. The metal detector does not always work properly. Some of the guards have walked through without detection while carrying a weapon.
- . 3. The Radiation Portal Monitor is not always working properly.
 - 4. CECo employe phonetic) talks disrespectfully about other employes around the guards.
- 5. Employes have been observed intentionally abusing dosimeters against the window shade and floor of the guard house.
- 6. Unauthorized contractors have been observed in vital areas. No positive action taken when this was reported.
- 7. A vital area door was reported broken and unlocked for several days before a guard was posted.
 - 8. Rolls of steel, scrap copper and sandpaper have been taken by employes without property passes.
- 9. Employes frequently depart without turning in security badges.
- 10. A guard had the guard force vital area door keys at home for 2 or 3 days.
- 11. Contrary to security procedures, the guard file cabinet is always unlocked.
 - 12. Employes and contractors are frequently observed in hard hat areas without hard hats.
- 13. Floor plans of the plant from the guard procedure are missing.
 - 14. CECo employed Trequently drives at a dangerously high rate of speed inside the Protected Area.
 - 15. Engineering drawings were found in an unoccupied, unsecured area.
- CC TV cameras are frequently inoperative because of weather or because they require maintenance.
- 17. The qualification test for the guards does not agree with the written procedures. Information in this record was deleted
 - 18. A lot of fish are killed. In accordance with the Freedom of Information Act, exemptions
 - 10. A vehicle was not provided for required guard patrols in extremely cold weather.
 - 20. The owner controlled ares gate #28 is broken.

- ✓21. Vital Area doors are frequently found intentionally left open.
 - 22. Doors to the administrative areas are frequently left unsecured.
 - 23. A Pinkerton guard offered to sell stolen motor oil.
- 24. Employes do not always check-out and check-in for lunch.
 - 25. The electric car for the guards was abused and has not been returned for the use of the guards.
- 26. Badge photos: some were expired and not replaced; one guard was photographed in civilian clothes.
 - 27. When visited the guards were jokingly making comments that someone should shoot him.
 - 28. One of the guards has recently purchased a new car and a house.

mul Secular That we NRC 3/2/17 Quad Cities Guard - James Mª Kay - Pinkerton

Guard - & Route; sel

startes


Made allegation; to James for Comm Ed

Interieured By James 12/25 for 2 1/2 hours

and then betylioned at office phone on 2/28. Has deary concerning incidents at site which mentioned problem areas - what could hoppen, not so much as what happened Confided in Warts to remain anonymous. See of Info See viol dry CECO empl + contractors Duestionable conduct of Penherton Gols Theft of station property High radiation chairles in Guard house Some items are aware of and take corrective action. Some distress are being looked into. metal detector does not work properly - Some quards can walk then w/o detection of Their weapon (master a way of doing. Information in this record was deleted FOIA-86-894 C/1 in accordance with the Freedom of Information Act, exemptions b+7 (c) FOIA- 86-894

Employees observed abusing dosimeters.
Unathorized Contractors in vital areas - nothing apparently done about it. (Station personnel maintain that distant alless looks were oftal replaced.
One V. A. cloor was broken + not repaired for several minths some employees depart site w/o leaving their security budges.
Thought that one guard may have Taken those VA heigh distring a broak in his shift. Gate house has ring w/ three steep which are passed from shift to shift.


Persons aware of the allegations




assured by of confidentiality. Said he is afraid alter guards may take represal actions Recently derived, moved here from Colif & studying for CPA exam. Plans to liave within a month. Twant, to avail any indication that me Koop identity was revealed to KRC

has requested Pinherton to check him out. Will continue to pursue ollegations to determine validity.

no called the talk to mi Kay well talk to or write press at the teme (but becouse of judged instability.) of judged instability.) Dedut went Penkerton or NRC to know about these items. appears to want to hold these enformation to himself. remove Mi-King from site! Penherton will report their plans of fendings to Time a few days. Will suggest to mc Kay that if he feels strongly on his allegations he may want to contact NRC deheatly recterated that as he total W Kay his name would not be sevealed to NRC during any conventions If we receive a call from me Kay that he wants to talk to us, we should not give impression we have beard his name mente. Quad-Cities-Investigation/Inspection of Physical Security Program




FOJA-86-894 A/1




- 8. May 6, 1977 Letter dated April 27, 1977 from ex-guard James E.


 McKay to Senator Percy sent to RIII by Headquarters.
- 9. May 12, 1977 Investigator interviewed McKay. This interview provided no new significant allegations regarding security. Other matters relating to radiation protection and plans operations are being evaluated.








.





FOJA-86-894 \ -93
1-27-77
16 She Henerable Charles H. Percy
United States Senator
600 E. Monroe St. Room 117
Spring Tild Ill. 62701 Ry. to 18 pages
Enclaid.

Senator Percy;

Information in this record was deleted in accordance with the Freedom of Information Act, exemptions 3

as registered vater and toppeying citizen of this great arentry The U.S. of Umerica I am informing you of some very important matters pertaining to athe Quad City Cordera Tuelian plant in Illinois. The info enclosed may be of vital ancera. one the past 2/2 menths T.V. and rewapiques have covered Just some of what I have listed. I think it is wise that you or somelarly of importance take particular natice of discrepances which I have pointed out in my notes over the past 4 menths. (my original note book with date, was taken out of my coat perhet when I loaned my coat to

I realize this will hat get my investigate you back, however, it may help in providing tighter security, measures on all nuclear plants throughout this nation.

CBS Action hows - "Security quand incident - was fired (maline area)

E.B. I. in west igation perceitly pending pales was fired - He apparently went to FBI, policie and runs papers with info
info a ment y it is correct.

news media, I went to 2 of my superiors, Ent it did no good, so I contacted Ds. melian longs also of CECO and Pinkuton's Que in Chicago, Ill. about 2 months ago. I have phone bills and numbers to prove this. Please read all info enclosed -Mary things did happen at micliar plant, and we are not liers as we have been called. Pinkerton and CECO have now one the part Im 1/2 months did improve security system, only due to perhaps my findings and poselly This Wed morning of 4/27/17 I called The F.B. I. Rockford office and talked with gave me the empression that it did not cover or include the FBI. End of discussion Thank you for your time and consideration. Kespertfully James E. McKey, 4/27/77 Threats scared me to gring to CECO .- Union and nin Union employees -Some My up indeed. CECO and Pinkerton There disconounce to clean up a laty

112 S.S.S.

SENATOR PERCY - Please Read.

I James E. McKay and filing for unemployment am pencation this May 2, 1977.

I was fired from my investigative yeb
with Pinkerton's, like on 4-20- ft by a
me. Jour of the Persia Pinkerton affere.

Mr. Sired me for allegedly releasing Confidential information on a Condoval Ill miclear Plant (CECO) to outside person who were not Pinkerton amployees. Mr. accused me of fabricating lies? in and fabre accurations about matters dealing with the mucleur plant accurity eyes tem. Mr. will would not or could not reveal the specific chails on persons I was to have contacted outside the Pinkerton Company.

More will be said on this later.

During my employment with Pinkertons, one. As a mucleal security guard of had discovered some, prositive, many, dis crepancys of a security mature in the months of Pan Feb and march of 1977. at the Quad City Condova Muclean plant (CECO). On a number of occasions a lt. Jem Sand my boss. Mr. Winformed me to leave well exough alme, and to keep my 6.D. mouth shut. I then made a minder of phone attempts to get intouch

Shes, m. C with ht. mys. of the Rock Is land office . on many calls to m. injuned the was to busy or not in, a he could not be disturbed. Then they would refu me to ht. in Command. This the ented at a dead end - I would not talk with Lt. only Calling too many Times at the Rock Saland affile to speak with ordered me to stop Calling there and to keep away from the office. He said he would standle all matters at the muclear plant so stop bothering persons at Rocke Island office. I thus called a nuclear Research Engineer of CZCO at the Chicago, Oll office, and informed listered him of my position. and he said the world have a af CECO- special agent of occ get un truck with me to possibly discuss The nature of such disreparega. mr. Called me on phone and be said he would inform you. Chicago office. cias ins. weid to wastelf to Eme out to the dinese to discus the nature of such incidents. At did. mr. also Called me and I told him Varically what had transpired over

the past ment is of Dec 1976, Jan, Als. and March, 77 at no time did I discuss with Police news media, nor F.O.T. the nature of such discrepancy sincerning the Cordova mirleur plant. about 4 weeks ago 734. 9:45. A.M. I CALLED F. B.I. AGENT mgs of Rock Island office Called me in- He said for my salety sake they were taking the all the muclese plant you and puttling on investigation He chined I was doing an out Atandery yob, and that he could live a good burn on his investigative from. I accepted. Dee my investigation dard # 19613 - It took about 3 weeks to get this and I som m. Talso Carries a Card of this type .- Suards do not get them-lyellow In color - with picture in middle) See photo copy I am not able to mention the nature of these discrepancys at this fine - there ever threats made against me - Union , s out side Contractors Has Vital area don Kup -: Union Figh and drinking on CECO property YAD The harris Huffman affair -KYS. THERE OUT. TELTOR degranes Ete. FOR of all floors in muclear plant-ABOUT 3 DA45. and meny others. St WAS FIRED ABOUT JAN 1977 - MISO SAID THAT KEYS-HE THEY ? > WERE OUT TO GET ME, DUE TO MY DISCOVERING TOOK THEM ADMITTED TO ME THAT NE HAD ENTIRE DISCREPANCYS. INSIDE LAYOUT OF CORDOUR NUCLEAR PLANT AND THAT HE COUND BET COPIES FOR ANYONE WHO WAS INTERESTED.

Claims I'm & Tier and he is fireing me for enouverly debricating all such discrepenting that were To have Taken place at the Cordona mucliar Plants: He Colled mea dam lun, and said I was not policy to get away with pomearing april 13 year record with Pindertons me. Claims he has top connections in State of Illinois. He served 20 years in U.S. army and was an Elg, and by cally no young fund The pared me if I would sufficient to a poly graph exumenation, and wisking place. I had not lied for fabricated such events that had transpired our the mentles at the muchal plant. I called them as I saw them occur and that is the fruth - Mr mosey was angued because I did not fen to get in truck with his Zeres alli did not try to Contact of office for Adid not Know Beople down that way, So I tried Pinke ton's Office. because of threat, made against one -Calliel and almost been run our in the dark by former Union Step Steward for CECO.

claimed in distance envistigative wack ground Cheers on me, and he caple to realize I was a lieu, and that I will not going to get away with such fabricating memi crest and bell stories. He said he knew important people in the "The mikey you will hat get away with weeken with such false face weather of Geven any Chance to explain. Mr. set next to me. He did not fine my side at all. He appeared soured. This inturiew lasted appeal 1/2 horer - m. said come on making who did you alk with out side Pinkerton; Ine? - I tald also dropped the Kint that a pro Certain persons (Mesicing me I gather little very pessibly the prosented over this sucident. I did not mention numes of Pinkertons Chicago affice on It was my under standing that the above 3 4 omen would investigate. I called (11:25 am on 4/23/77 -There was no basis a cause for alasm - His ITwas investigation revealed very little on what a wait had come up with I winter is very Time Mis informed. CECO and Pinkuter of Ine had about 8 weeks to get things cleaned up or covered up - now I'm a lier and nenery the things I mentioned sere accurred. Very strang indeed. Sweath move on their part. Mys. of RII office, takes me off guard duty

my NOTE BOOK. WAS TAKEN OUT OF my word parci. MISOSTON FIGHTIME AND ANDRESS ON CELD NEWS PREMISES - Eig. The AFFINA .- I TURNED IN 32008 REPORT OF WEOMS. A BOURT - OUTSIDE CONTRICTORS AND SUME CERO 1 - 20160 - Now UNISE PULL THEISE IS A CONTENTS - "LIKE WE HERE OR6. NEMED MCKEY" BIS TOKE! 17120 72401.25. BADGES HIDDEN, OR TURNED BACKGURIOS LNIGht SO PICTURE COULD NOT BE SEEN. SOMETIMES Wirs JEGGAND THEM SOME WILESE ELSE OR JUST FORGOT THOS HITO DO PICTURE BADGES, THEY LEFT THERE IF I CALLED SOMEONIT-THEY SAID GO GET SCREWED SIMETHIES THEY TEOK BADGES HOME OR LOST THOSE. .20160-ما مين له whe pipe. Spoin Him Set of GOU KNEW OF SOME OF THE THINGS THAT 1 pretruy WISHING LUTUE GONE ON AT CECO CORDONA PRINT you would BE ASTOUNDED." Todd'in my estives. OPINION GAN'T BE TRUSTED. UNPREDICTABLE MAN. MANY GUARDS PREST QUIT OR ARE FIRED OVER PERIOD OF ZURS. GUARDS APPINENTLY ALL WALKED OFF THE JOB SOMETHINE BACK. KEFT PRIMIT UN SUARDED -Satis SHOULD TAKE NEW GURROS ARGUND AND SHOW THEY THE THINGS THAT SHOULD FIND BE DONE. THEY DON'T - THE OLDER GUARDS BREAK THEM IN INSTEAD- THEY KEMEN TOO ining distilled to the Not Tour PROPERLY WHAT IS EXPECTED OF THEM. MIS 621080, MISINFORMED. Etc. NOT LEARNING THE RIGHT METHODS OF SECURITY PROCEDURES.

(over)

Chan my chammy Somebody in Plakerton, has given VAD. Keys to outside un soit appears outside Contractor, has the state contractor, has the state contractor, has the state out is bet interest in the service outside.

I this surrement the name is me 2 days

8/4 he was similar process or outside.

100 uns similar process or outside.

NOT GETTING CLEANED PROPERTY - DUE TO
TOO SMALL A CAPACITY FOR TOO MINNY
LBS. OF CONTRIVINATED UNIFORMS.

MEN CHORRENDS IN THERE 2 BLACK MEN

AND > STINEOUS CONTAINANTED

ITEM, SHOES ETE ACROSS RM. THEY STUFF

MICHINES TOO FULC. - OVER LORDED, CARELESS IN

DOOR OT WEST SNO. BY CONTROL RIN.
LINED GOING OUT ONTO ROOF - UNLOCKED
ENSY FOR RECON TERM TO GAIN CONTROL

AND THE OVER PLANT CONTROL RM. THIS DOOR

SHOULD BE KEPT LOCKED AT ALL TIMES.

THIS DOOR GOES ON ONTO ROOF.

CONCEALED AND SHOWING POLICE PERMITTED

TO ENTER INSIDE PRANT WITH WENDOUS ACTUS

CONCEALED AND SHOWING . ARE NOT REQUIRED

TO CH WENDOWS.

VAD DOORS FOUND OPEN OR UNLOUSED OVER PAST 4 MONTHS WERE.

DOOR FACING NORTH.

OCCASIONS.

SMALL DOR ACROSS FROM

Doce

ALERT WORK AT 6. AM. STORY

AND ME SOME OF 6 AM STORY

PURCE - VAD KLEYS MYSSING

THAT DAY AND THE APPROX 2 Chays

AFTER SITION APPROPRIENT TO THE MENT TO THE PROPRIENT THE MENT HOME BY MISTIMES TOR ME.

Soft ALL LEVELS INSIDE NUCLEUR PLANT.
GICH

GER HOD 5 PAGES MISSING OF THE SPECIFIC

SECTION DESTRUCT DERWINDS OF SACH DEST'S FUNCTION

DESTRUCTION DERWINDS OF THE COULD GET AND

LYMOUTEST PHOTO COPY ALL OF THE INSIDES OF NUCLEUR

EIGHT PLANT DERWINGS- IF I WARTED THEM. HE TOOK

LEVEL A PLANT DERWINGS- IF I WARTED THEM. HE TOOK

MANY HOUSE THEM PROTOSES

MANY HOUSE THEM THEM.

VITAL AREA SOOR (VAD).

HIT BY TOW TRUCK: I TOWN IT BUSTED- WOULD

NOT LOCK NOR OLOSE ALL THE WILL, 3/2 DEUS

OR SO KATER DOOR IS FINING FIXED - NO CUMENS

STATIONED ON ROOPS WHEN I CAMP DIEK TO

WIRK. FXCUSE WAS IMPINIT SAID THEY LALKED

PRIETS TO FIX DOOR, SOTHEY TOLD ME. DOORWIS

UNDURSOED FOR A LENGTIME - VAD DOOR.

SIME CECO EMPLOYESS AND OTHERS - GO HOME

WITH HIGH RAD RESOURCE IN HAMOS, FEET,

OKOTHES - SHIFT SICE.

TO GUMAN HOUSE - LET THEM GO HOME.

VERY LITTLE SEARCH OF PEOPLE AND VEHICLES - DICE

A MONTH. MANY THIES WERE STOLEN OUT OF NUCLEUR

PRANT. (OVA)

SCREEN NOT WORKERS PROPERTY OF INTERESTED FLOWER OF INTERESTED INTERESTED OF INTERESTED PROPERTY OF INTERESTED.

7/

175 TIS LOCKS - THEY COUT USE TO OPEN 6-1 LOCKS BUT CAN USE "S" KEY FOR 6-1 KEY.

FOR A LONG TIME GITE #28 OUTER - IN BAD NEED OF REMAINE - POSSIBLY WILL MAKE RADINTO

FENSE WEST SIDE SOUTH SIDE MENT WETTE'S

2068 PROTECTED AREA - NOT MISH ENOUGH

I COULD STIND RYE LEVEL WITH IT AND CLIMB

OVER INTO PROTECTED AREA. FINALLY, THEY EECO

CORRECTED THIS AFTER A LONG TIME -

OUTSIDE CONTRICTORS COMING OUT OF ELECTRIC PM,

8 MED & CABLE PM. - THEY SAID THEY ALWRYS HAD

NEWS - THEY ARE NOT TO BE THERE. THEY SHID

ONE OF THOSE EVISE GUY GUMES - BETTER GO

CARE FULL I WAS TOLO.

WAD DOORS PROPED OPEN WITH ROCKS AND
BLOTS KEFT IN DOORS. THIS ACTUALLY HAPPENED
ON MANY OCCUSIONS

SCRAP LING ALLOUEN OECO AREA. -6000 SCRAP.

AND OTHER CECO EMPLOYEES (CECO EMPLOYEE)

SJA VAND TOO BUDDY, BUDDY FIRE SECURITY

PURIOSES.

BLEW SENS ON RECIRCULAR PUMPS ALICATO CAGAIN) - POUTE SEVENS MINE CORSON -POINT OFFINATIONS MINISTRY ROOMS - MINISTRUT DOING MICHE TOB AS SHOULD IZE.

2-10-77 AT OUSO AM. 11/25.

COMPUTER SETTINGS ON BODY COUNTER IN ROOM ROOM

LAB. - TRANSERED WITH - INCORRECT RESENTINGS -
CLUTTERING UP DOOR WAY AND HIML WAY WITH

HIGHRY RADIO RETIVE TOOLS, AND EQUID. -

BLOG. "C" LEFT OPEN (DOOR PROPED OPEN) ALL
LIGHTS BURNING) -CAGES ALL UNLOCKED 3-30-77
WILL MINCE WAS OUT IN THAT AREA-THEN.

AT. 10:10 p.m. Sqt. MET A SMALL SKART

MAN WITH GHASSES - NE APPEARED TO BE A CECO

ENDLOGEE - AT TRACKWAY #2 BOOR. MAN WAS

SMOKING A CIGAR. THEY HEADED IN DIRECTION OF

TRAILORS. OUTSIDE, Sqt. MADE ROUNDS THAT

NIGHT. - SOMETHING WAS UP.

CRACK. IN WHITER FEED LINE TO PEACTOR UNIT # 1

INSPECTOR FIS IN 3/28/77. ALSO MORE CRACKS
IN REACTOR. COMPRESSOR DOOR IT SEEMS WAS

BLOWN - 49 USS PRESS. - SEAL DAMAGED - IT SEEMS.

BOTH ARE HIGH. 2/28/77 NOT FUNCTIONING

ON 3-18-17: 3-19-17 UNIT # 1 REFUEL STAGES

FOR 12/16 FUEL TEST PROBRAM PROVE
(LARGE BRACK BOOKS) LEFT OUT ON TOP OF

BONFERENCE RIM. TABLE - DIM LICHTS BURNING.

NO ONE 118 108 - DOOR PROPER OPEN - ERRY NICESS

TO THRE THESE USEY IMPERIENT BOOKS.

Service and the Charles of

SEE MEXT PAGE

Badeges thered award or under their gaments BAdales Not Properly Desplayed UNIT I REFUEL OUTTIES CANTOS BUREN FEREST , 32 SPRING 1977 FOEL TEST PROFINITS ALSO KEFTOUT IN COMF. R.M. -NO ONE MEDULA DARK- ROOM PROMED OPEN. FORSISNERS WELLS IN ON THE WEEK END-(INDIA) ? > OTHERS. of 6.E. HAD CAMERA INSIDE PLANT SINCE 3-25-77 - 175 NOW 3-31-77 - HE APPARENTLY HAS A CARD FOR PROPER AUTHORIZATION- PINKERTON'S WAS NOT INFORMED OF THIS. SOMEONE IS TAKING SCRAP, COPPER TURING OUT OF IM SHOP. - NOT CERTAIN BUT AT THINES has TORNUP PASSES FOR TRIBUGE THINGS OUT OF PLANT. ALSO ROLLS OR SANDED ABOUT 1/2 to 1" IN DIMERTIE GOING OUT OF By Con CECO EMPLOYEES. DOSIMETERS - PHO MAN 32.40 SHR THIS N CLOTHES \$ 6UA120 TOGET RAD. TAND OTHERS THRESWING DOSIMETERS COUNT. LIKE DARTS AT WINDOWS HMOES ACROSS THE BIM. - REALLY THROWS DOSIMETERS OUT OF PROPER EDUNTING FOR RHDIATION COUNTS. ILTURE BADGES THAT HIS LONG EXPIRED -STILL IN RACKS. NOT PULLED. ITS OFF. - PEOPLE PASSING METIN DETECTOR-7 TURUUKH - 1211 CU. UNE WITH UR THINKS PECAIN (11.1.) PHSS THROUGH WITH GUNS OR BOMBS. CIKEMED. SECURITY GUARD HOUSE - T.V. CAMMENS ALL TO SECURITY GUARD HOUSE - T.V. CAMMENS ALL TO SECURITY BURE - 25 3 T.V. CAMMENS DE LAT DE LAT DE TOTAL TO THE PROPERTY PED - ACCESSED - 25 15 2913.

. 13

ASAM ALMOST RAN OUSAME AT SO. LUNST

CORNER OF BILER RAN. 2-21-77

MISSED THIS WILL BETHE 300 TIME HE HAS AUMOST

MICHES HIT ME WHILL DRIVENS PECKESSLY IN AND

VERYOUSE ABSUND PRINT AREA: - HE HAS A FROM DISLIPE

FOR ME.

REVERIS VERY IMPORTANT SECURITY MATTERS

REVERIS VERY IMPORTANT SECURITY MATTERS

PERTAINING TO SECURITY OF NOCLETIC PLANT.

ON PROJECT AND MEMS 1977. ALSO, ON CBS. 4/26/77

ON PROJECT ACTION MEMS CHAPTREL 4 - POSSIBLE FIRT. MUESTIGNTION NUMBER OF ENERGUENTRY - EATH BOOS ON GUARD HOUSE MATTERS.

A PREGUENTRY - EATH BOOS ON GUARD HOUSE MATTERS.

4 1700 100 - 3,000 10 20,000 millie Fems.

TOLO NOT TO WRITE-UP VITAL APEA DOSES THE WERE FOUND OPEN OR UNLCCUED ON PEROPTS FORMS. JUST ATTICK PIECE OF PRIVER TO UPPER KEFT HAND CORNER- AND WRITE IT ON THERE. OTHERWISE IF IT GOES ON PEPONTS V.S. GOVERN MENT FINES CECO CER OPEN OR UNIOCIZED JUDIES DOOR. (E) 1EST.DS 000 0002. WAS ORDERED BY SOF TO LUMIE ROUNDS 40° to 60° BELOW ZERO WEATHER NO TRANS PORTATION FOR 15t. 2Nd. DRIES -SAID WALK OR USE OUR OUN CAR- TUSED MY CAR. SIGNED CIR IN. WE WERE TO FAND MYSELF. GUIT PINKERTONS - GOT ANTHUR JOB.

WATER ON FLOOR IN CRIB HOUSE, BOILER EM, & LIFT STATION-A GOOD DEAL OF THE TWILE.

(over)

BOILER FOR AND KIET STATIOD.

MALTUNETON OF DEFUSE GATES-AT SIMPLE

GREEN AND BLACK HOSES STRUNG ACROSS

FLUM BRIDGE WIGHT APPER WIGHT. OVER TO

SAMPLE BLOG.

TOO MANY TIMES EMPLOYEES ARE CHECKING IN AND OUT OF PRINT LOR 3 TIMES EN A DRY-THIS LUNG NOT BEING LOGGE IN OROUT FOR EVER TIME.

MANY TIMES WILL MINCE SPENOS 2 to 3 HOS.

AT A TIME IN SUMMO LOUSE THEREOF WITH

SOT. HE ONCE LEADED VINDS THERE.

CUARDS REQUED LITTLE ELECTRIC CAR"
RECULESS, RODDING, E.E. - ALLIS ON FOOT

NOW. - RUN ILERE, RUN THERE, REPRIRITION

TOLD ME GUARDS RUIN CAR.

2-21-77 TIPPING Soft SOME TIMES AT 2012 4 WOULD BE
PENETRATED SOMETIME AROUND 6:30 AND 7:30 A.M.

ALL KICIOS OF BUSINESS DOCUMENTS SCRITTURED

MINO FRONTING ARCOUND FRANCE INSIDE AND

OUTSIDE OF SWITCH YARD - 2-22-77.

HUNDREDS OF SHEETS OF PAPER OUT THEIR.

DIFTSO - 1969, 1970, 1971, 1972 ctc.

PRICES, PART NUMBERS., REQUISITIONS - PART

NUMBERS AND DES CRIPTIONS.

MEE MEN & CO. PRESIDENT COMMON THIS

NOTO IS MINORING FOR NO MANAGE - JOHE AMENGE

BURGOS - MAN TO BOYER MESSINEMS HELICOPTER

ON 2-22-17 - THIS IS NOT FURNY.

SMELLED SMEAUC ODOR OF GAS LEARING COMES

9/21/11 AT OUTSIDE CORNER OF SO WEST SIDE OF

BOILER RIM. CORNER. - DIMILL MISSE HOUSE.

THIS GUAS REPORTED - THEY SMY MODILY.

NO SMELL OF GAS. - THIS HAPPENS OFF ANDONS.

ACID UN FLOOR TUST INSIDE TRANSMINE!

200R 2-22-77, IT COURS SUBSTRATING

MAT - LEFT THERE FOR ABOUT 2 HIS - THEN

IMPIRIT. CASHE AND PUT BAYING SOON ON IT.

HORD HITS NOT BEING WORD IN HARD HAT KIREA, IF I CALLED THEM ON IT -THEY SAY; GO GET SCREWED."

PLANT NEEDS HOUSING-KEEPING INSIDE AND OUTSIDE.
THEY COULD LEARN FROM CALIE. PLANTS.

CONTROL BOXES INSIDE H2 FARM - GAUGES EXPOSED
TO BAD WEATHER.

BOILER RM, CRIB HOUSE DOORS FOUND UNLOCKED. SO MSO RAD WHETE DOORS.

PRINT OUT - HIDDEN IN HIS LUNCH BOX.

AROUT SHOOTING OR KULING PEOPLE. THEIR
BEHAVIOR AND ATTITUDES IS SCARY.

Hog .

Then nuclear system Inc Field Services -Third not had QSP Training as of 4/1/77

THEY DO NOT KEED THEIR WORD. DEVISOS, OSCEDITUE.

ON A SELIZER ONLY SONIE CARS AND TRUCKS ARE SEARCHED OTHERS MILE NOT IN -CONSISTENCY -OFF AND ON.

TOLD MIE HE HID OVERS

HISOD CUSICITY OF PINISSITON UNIFORMS

THIST HID NOT BEEN ESTURINED TO MININ

OFFICE - WHEN GURRES SUPPOSEDLY

AND OFFICE THERE TORS.

CHECKS COMMING ASOUT THERE PRY

CHECKS COMMING 24 4 DAYS ARTE - ALSO

SHURT CHANGED IN HAS MUDININEY ON THEIR

PRAY CHS.

DN SOME OCCASIONS - MIL LISATS OUT IN BOILER RM. WILL MALLE ON DUTY- TURNING OFF LIGHTS.

DOORS LEFT UNLOCKED -OPEN AT OFF GAS

FOUND DIS FLOOR SINTE IN ACADEMANTE FROM

ON NEIBURGE LLOOD INVESTIBATIONS-I FOUND
NEWESS OF FORMER CUMICOS NEVER LIVED

NOT SUCK APORESSES-NOT LEAST NEISHOUSE
RIEVER HOMED OF THOSE BIYL GETTHY,
WERE HIREO TO DO SECURLUM WORKSONNY N

Internative of Alleria of Char	o Chammaian
University of illinois at Cliban	ia-Onampaign
OMANITIEE ON ACCOUNTANCY OA Administration Building Thene, Illinois 61801 This is ruta	
This is here	September 30, 1976
me time at	ruelear plant.
Pline read	and & Brelpayer
part of Security operations at Plane read Still no	result. 4/27/17
Dear Mr. McKay:	
I an	
. I as	
· · · · · · · · · · · · · · · · · · ·	
I have asked the	
submitted.	
Applications for the	0 0
Very trul	y yours.
	argaret-Richarden
	rgaret Richardson, Secreta on Accountancy
MR:1g	
UNIVERSITY OF ILLINOIS AT URBANA-CHAMPAIGN	Card #4
Committee on Accountancy 1008. Administration	1218
· Date	JUN 24 1976
. Date	

TO THE

We are pleased to inform you that

A permit and instructions will be sent to you at a later date. For your convenience, and program is enclosed.

Very truly yours,

E. J. SMITH, Secretary Committee on Accountancy 14



UNITED STATES CIVIL SERVICE COMMISSION

CHICAGO AREA OFFILE
EVERETT MCKINLEY DIRKSEN SUILDING
219 SOUTH DEARBORN STREET
CHICAGO, ILLINOIS 80604


Received 1/15/17


IN HETLY PLEASE ACTER TO

CH

-

1-14-77





DATE AND TIME:

REPORT TO:

John Nieminski AREA HANAGER



UNITED STATES CIVIL SERVICE COMMISSION


CHICAGO AREA OFFICE
EVERETT MCKINLEY DIRKSEN BUILDING
219 SOUTH DEARBORN STREET
CHICAGO, ILLINDIS 60604

January 14, 1977

YOUR REFERENCE

Ronorable Charles H. Percy United States Senator 600 E. Monroe St., Room 117 -----Springfield, IL 62701

Dear Senator Percy:



If I can be of further assistance in this regard, please contact me.

Sincerely yours,

John niemensie

John Nieminski AREA MANAGER

also - I never did receive time and place to take exam even as of this date Seneth Percy - 4/27/17.