

2649 Yorkshire Road
Birmingham, Michigan
July 9, 1986

Ms. Evelyn Matson
United States Nuclear Regulatory Commission
Licensing Branch
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Ms. Matson:

Please find enclosed the close-out survey for Pontiac Imaging, 530 West Huron, Pontiac, Michigan. This survey is provided as an addendum to a recent amendment to NRC License No. 21-17781-01, Control No. 81461. Should you require any additional information, please do not hesitate to contact me.

Sincerely,

Catherine Warmelink

Catherine Warmelink, M.S.
Physics Consultant

U.S. N.R.C.
LIC. FEE MON. BRANCH

'86 JUL 16 P2:17

RECEIVED

RECEIVED BY LFMS	
Date	7/16/86
Log	July-18-III
By	Jalques
Date Completed	7/12/86

FEE NOT REQUIRED

*close out survey
continuation of prev.
request*

RECEIVED


JUL 14 1986

REGION III

JUL 14 1986

8609290411 860827
REG3 LIC30
21-17781-01 PDR

CONTROL NO. 81685



CLOSE-OUT SURVEY 6/19/86
 Pontiac Imaging
 530 West Huron
 Pontiac, Michigan
 NRC License #21-17781-01

Area #	Survey Meter Reading (mR/h)	Swipe Result
1	0.02	Negative
2	0.03	Negative
3	0.03	Negative
4	0.02	Negative
5	0.04	Negative
6	0.02	Negative
7	0.03	Negative

Instrumentation used for the area survey and swipe test were a Victoreen GM Survey Meter, Model 498, Serial 738M, and a Picker Spectroscaler 4R/ NaI(Tl) well counter, respectively. No evidence was found which indicates the presence of ≥ 0.005 uCi on any wipe.

CONTROL NO. 81685