

TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201

September 29, 1986

WILLIAM G. COUNSIL
EXECUTIVE VICE PRESIDENT

Mr. Eric H. Johnson, Director
Division of Reactor Safety and Projects
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012


SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NO. 50-445
REINFORCING STEEL IN UNIT 1 REACTOR CAVITY WALL
SDAR: CP-86-57 (INTERIM REPORT)

Dear Mr. Johnson:

On August 29, 1986, we verbally notified your Mr. T. Westerman of a deficiency involving the reinforcing steel in the Unit 1 reactor cavity wall. This is an interim report of a potentially reportable item under the provisions of 10CFR50.55(e).

During construction of the Unit 1 reactor cavity wall, additional reinforcing steel was added to a drawing and subsequently deleted without any record of design calculations being made. We are continuing our evaluation and anticipate submitting our next report by November 1, 1986.

Very truly yours,



W. G. Council

JCH/amb

c - NRC Region IV (0 + 1 copy)

Director, Inspection and Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8610100039 860929
PDR ADOCK 05000445
S PDR

86-1102

1/0 IE-27