Report P	eri	od	MAR	1986
----------	-----	----	-----	------

UNIT SHUTDOWNS / REDUCTIONS

****	****	*****	****	*****	
*	WASHI	NGTON	NUCLE	AD 2	
*****	****	- WWW	HOCLE	MK	*

No.	Date	Туре	Hours	Reason	Method	LER Number	System	Companent	***************************************
85-02F	07/01/85	F	0.0	A	5		СВ	PUMPXX	POWER OUTPUT LIMITED TO 72% DUE TO THE
86-01	03/14/86	F	16.2	G	3	86-003	RB .		REACTOR SCRAMED AT 51% POWER DURING THE PREFORMANCE OF THE AVERAGE POWER RANGE MONITORING (APRM) CHANNEL SURVEILLANCE. THE WRONG APRM CHANNEL WAS INADVERTENTLY SUBSEQUENTLY CAUSED THE CONTROL OF THE CO
86-02	03/15/86	s	381.7	F	9				SUBSEQUENTLY CAUSED THE SCRAM.
86-03	03/31/86	S	24.0	С	9				UNIT REMAINED OFFLINE FOR LACK OF POWER DEMAND. UNIT ENTERED REFUELING/MAINTENANCE OUTAGE.

********* * SUMMARY *
******** WNP-2 EXPERIENCED & OUTAGES AND 1 POWER REDUCTION IN MARCH.

Туре	Reason	Method	System & Communication		
F-Forced S-Sched	A-Equip Failure F-Admin B-Maint or Test G-Oper Error C-Refueling H-Other D-Regulatory Restriction E-Operator Training & License Examination	1-M1	Preparation of		

PAGE 2-389

8610100466 860812 PDR ADDCK 05000397 R

DOCKET NO.

50-397

UNIT NAME

DATE

5/1/86 LB Hutchison.

COMPLETED BY

TELEPHONE (509)377-2486

REPORT	PERIOD.	MARCH	1986	
		month,	year	

NO.	DATE 1	YPE	HOURS	REASON	METHOD	LER NUMBER	SYSTEM	COMPONENT	CAUSE & CORRECTIVE ACTION TO PREVENT RECURREN
85-02P	7/1/85	F	0	Α	5		СВ	PUMPXX	POWER OUTPUT LIMITED TO 72% DUE TO THE INOPERABILITY OF "B" RRC PUMP
86-01	3/14/86	F	16.2	G	. 3	86-003	RB	INSTRU only orlage of month	REACTOR SCRAMED AT 51% POWER DURING THE PERFORMANCE OF THE AVERAGE POWER RANGE MONITORING (APRM) CHANNEL SURVEILLANCE. THE WRONG APRM CHANNEL WAS INADVERTENTLY PLACED IN A TEST MODE AND LOGIC NOT RESET WHICH SUBSEQUENTLY CAUSED THE SCRAM.
86-02	3/15/86	S	381.7	F	9			- (UNIT REMAINED OFF LINE DUE TO A LACK OF POWER DEMAND
86-03	3/31/86	S	24	С	ù		- Con	invotion of	UNIT ENTERED REFUELING/MAINTENANCE OUTAGE

UNIT SHUTDOWNS / REDUCTIONS

| SUMMARY |

WNP-2 OPERATED AT A REDUCED POWER LEVEL UNTIL THE FORCED OUTAGE OF 3/14/86. THE PLANT WAS ON RESERVE SHUTDOWN 3/15 THROUGH 3/30 WITH REFUELING & MAINTENANCE OUTAGE STARTING 3/31/86.

TYPE	REASON		METHOD	SYSTEM & COMPONENT		
F-Forced	A-Equip Failure .	F-Admin	1-Manual	Exhibit F & H		
S-Sched	B-Maint or Test	G-Oper Error	2-Manual Scram	Instructions for		
	C-Refueling	H-Other	3-Auto Scram	Preparation of		
	D-Regulatory Restriction		4-Continued	Data Entry Sheet		
**	E-Operator Training		5-Reduced Load	Licensee Event Report		
	& License Examination	n	9-Other	(LER) File (NUREG-0161)		