

12 JUN 1987

Docket No.. 030-29216

License No. 37-27829-01

Moyer Instruments, Inc.
ATTN: James S. Moyer
President
417 E. Elm Street
Tamaqua, Pennsylvania 18252

Gentlemen:

Subject: Routine Inspection No. 87-001

On March 16, 1987, R. H. Ladun of this office conducted a routine inspection at Reading Anthracite Coal Company Field Site, Pottsville, Pennsylvania of activities authorized by the above listed NRC license. The inspection was an examination of your licensed activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selective examination of representative records. The findings of the inspection were discussed with yourself at the conclusion of the inspection.

Within the scope of this inspection, no violations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter will be placed in the Public Document Room. No reply to this letter is required.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:
John D. Kinneman

John D. Kinneman, Chief
Nuclear Materials Safety Section A
Division of Radiation Safety
and Safeguards

cc: Public Document Room (PDR)
Nuclear Safety Information Center (NSIC)
Commonwealth of Pennsylvania

OFFICIAL RECORD COPY

ML DL MOYER - 0001.0.0
06/06/87

8704180345 870612
REQ1 LIC30
37-27829-01 PDR

RETURN ORIGINAL TO
REGION I

1/0
IE:07

Moyer Instruments, Inc.

2

12 JUN 1987

bcc:
Region I Docket Room (w/concurrences)
Management Assistant, DRMA


DRSS:RI
Ladun
6/10/87

DRSS:RI
JKinneman
6/10/87

OFFICIAL RECORD COPY

ML DL MOYER - 0002.0.0
06/06/87