


Log # TXX-6125
File # 10110
908.3

TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER - 400 NORTH OLIVE STREET, L.B. 81 - DALLAS, TEXAS 75201

November 26, 1986

WILLIAM G. COUNCIL
EXECUTIVE VICE PRESIDENT



Mr. Eric H. Johnson, Director
Division of Reactor Safety and Projects
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
CABLE PULLING TENSION
SDAR: CP-86-71 (INTERIM REPORT)

Dear Mr. Johnson:

On October 2, 1986, we verbally notified your Mr. Ian Barnes of a deficiency regarding electrical cable pulling. This is an interim report of a potentially reportable item under the provision of 10CFR50.55(e). We have submitted an interim report logged TXX-6065, dated October 31, 1986.

Concerns exist involving the possibility of some cables being damaged because cable installation procedures do not address tension limits for vertical cable pulls and subsequent pulls into conduits with previously pulled cables. Evaluation activities noted in our previous response have proceeded to the point that changes in the construction procedures are required. Our evaluation has not progressed, however, to the extent an assessment of the effects of this deficiency on the safety of plant operations can be completed. This phase of the evaluation should be completed by February 2, 1987.

We anticipate submitting our next report by February 25, 1987.

Very truly yours,

W. G. Council

JCH/mlh

c - NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8612170023 861126
PDR ADOCK 05000445
S PDR

86-1403

1/0 IE-27