

OCT 09 1986

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Joe Williams, Jr.
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Mr. T. Ploski and others of this office on September 22-24, 1986, of activities at the Davis-Besse Nuclear Power Station, authorized by NRC Operating License No. NPF-3, and to the discussion of our findings with you and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W.D. Shafer"

8610160431 861009
PDR ADCK 05000346
G PDR

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection Report
No. 50-346/86020(DRSS)

See Attached Distribution

RIII
JP
Ploski/l
yes

RIII
WGS
Snell
yes

RIII
Jackiw
1/9

RIII
Shafer

IE35
11

OCT 09 1986

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of Ohio

Robert H. Quillin, Ohio

Department of Health

D. Matthews, EPB, OIE

W. Weaver, FEMA, RV